<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action													
30-045-09 128 Release Notification						OPERATOR							
Name of Company: BP						Contact: Courtney Cochran							
Address: 200 Energy Court, Farmington, NM 87401						Telephone No.: 326-9457							
Facility Name: Florance K29						Facility Type: natural gas well API # 3004509128							
Surface Owner: Federal Mineral Owner						: Federal Lease No. SF-078385							
				LOCA	ATION	OF RE	LEASE						
Unit Letter	tter Section Township Range Feet from the Nort			North/	n/South Line   Feet from the   East/V			West Line   County:					
K	25	T30N	R08W	1500	South		1550	West		San Juan			
	l	La	titudo 2	L 6 77000	I anaitud	107.62094		# · · · ·	<u> </u>				
Latitude_36.77999Longitude107.63084													
Type of Release: natural gas  NATURE OF RELEASE  Volume of Release: 230 MCF  Volume Recovered: no gas recovered													
Source of Release: natural gas  Source of Release: suction scrubber dump valve						Date and Hour of Occurrence:			Date and Hour of Discovery: 11/3/2011				
						11/2/2011 – 11/3/2011 (31 hrs)							
Was Immediate Notice Given?  ☐ Yes ☐ No ☒ Not Required						11/2/2011 – 11/3/2011 (31 hrs )  If YES, To Whom?  Date and Hour:							
By Whom?						Date and Hour:							
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
Was a Watercourse Reached?  Yes No  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.* Suction scrubber dump valve hung open. Fluid was found in the line to the controller and the snap. Well is shut-in and a RCFA will be conducted.													
Describe Cause of Problem and Remedial Action Taken.* Suction scrubber dump valve hung open. Fluid was found in the line to the controller and the													
snap. Well is shut-in and a RCFA will be conducted.  Describe Area Affected and Cleanup Action Taken.*													
The gas released dissipated into the atmosphere so no clean-up action was possible.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
							OIL CONSERVATION DIVISION						
Signature:						Approved by District Supervisor							
Printed Name	: Courtney	Cochran											
Title: Environmental Challenger						Approval Date: 1/12/2012 Expiration Date:							
E-mail Addre	ess: Courtne	y.Cochran@b			Conditions of Approval:				Attached	Attached			

Phone: 326-9457

November 7, 2011 \* Attach Additional Sheets If Necessary

nJK 1201238252