

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-09464

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Co.	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington NM 87401	Telephone No.: 505-326-9457
Facility Name: Florance I 38	Facility Type: natural gas well API # 3004509464

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 079511-A
------------------------	------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter L	Section 14	Township 30N	Range 08W	Feet from the 1650	North/South Line South	Feet from the 990	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.80889 Longitude 107.64983

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 146 MCF	Volume Recovered: none
Source of Release: suction line	Date and Hour of Occurrence: 11/20/2011 16hrs	Date and Hour of Discovery: 11/21/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD NOV 30 '11	

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.

DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

The inlet to the suction scrubber was leaking through a crack in the 2 inch nipple between the suction valve and ball valve. The compressor was shut down and the nipple will be replaced.

Describe Area Affected and Cleanup Action Taken *

Natural gas dissipated into the atmosphere so no clean up was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor: 	
Title: Environmental Challenger	Approval Date: 1/12/2012	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval.	Attached <input type="checkbox"/>
Date: 11/29/2011	Phone: 326-9457	

* Attach Additional Sheets If Necessary

nJK1201241094