

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED

RCVD DEC 22 '11

OIL CONS. DIV.

DIST. 3

Sundry Notices and Reports on Wells

DEC 16 2011

Farmington Field Office
Bureau of Land Management1. Type of Well
GAS6. Lease Number
NMSF-078387-A
If Indian, All. or
Tribe Name

2. Name of Operator

7. Unit Agreement Name

ConocoPhillips

3. Address & Phone No. of Operator

8. Well Name & Number
Kernaghan B 4A

PO Box 4289, Farmington, NM 87499 (505) 326-9700

9. API Well No.

30-045-22422

4. Location of Well, Footage, Sec., T, R, M

10. Field and Pool
Blanco Mesaverde

Unit P (SESE), 830' FSL & 890' FEL, Section 30, T31N, R8W, NMPM

11. County and State
San Juan, NM**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA**

Type of Submission

Type of Action

☐ Notice of Intent☐ Abandonment☐ Change of Plans☒ Other - Plugback MV / TA☒ Subsequent Report☐ Recompletion☐ New Construction☐ Final Abandonment☐ Plugging☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut off☐ Altering Casing☐ Conversion to Injection**13. Describe Proposed or Completed Operations**

The Mesaverde formation of the subject well was plugbacked and the wellbore temporary abandoned for future uphole potential on 12/2/2011. The MIT chart is attached.

14. I hereby certify that the foregoing is true and correct.Signed Crystal Tafoya Crystal TafoyaTitle Staff Regulatory Technician Date 12/15/2011

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD

DEC 20 2011

NMOC**FARMINGTON FIELD OFFICE**

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 * fax: 505-325-1211

Conoco Phillips
Kernaghan B #4 A

December 2, 2011
Page 1 of 1

830' FSL and 890' FEL, Section 30, T-31-N, R-8-W
San Juan County, NM
Lease Number: NMSF-078387-A
API #30-045-22422

Plug and Abandonment Report Notified NMOCD and BLM on 11/29/11

Plug and Abandonment Summary:

- 11/29/11 Road rig and equipment to location. SDFD.
- 11/30/11 Check well pressures: bradenhead 0#, casing 100# and tubing 95#. RU Phoenix slick line. RIH with 906 gauge ring to 4835', unable to get down. RIH with 175 gauge ring to EOT 5867'. RD slick line. RU rig and equipment. Check well pressures, same. ND wellhead. NU BOP and test. TOH and tally 81 stands 2-3/8" tubing. LD 20 joints. SI well. SDFD.
- 12/1/11 Check well pressures: bradenhead 0#, casing 85# and tubing 0#. RU blow down lines, blow well down. Test BOP. Round trip 4 1/2" casing scraper. PU 4 1/2" DHS cement retainer and TIH to 5003'; set DHCR. Pressure test to 1000#. RU and attempt to chart test casing; unable to test pressure. Let wellbore stabilize. PU with 10 stands of tubing. SI well. SDFD.
- 12/2/11 Open up well; no pressure. RU. Test BOP. TIH with 10 stands and tag CR at 5003'. Establish circulation with 1/2 bbl. RU chart test and pressure test casing to 650#.
Plug #1 with CR at 5003' spot 23 sxs (27.14 cf) Class B cement inside casing from 5003' to 4700' to cover the Mesaverde perforations and top.
TOH and LD all tubing. RD. ND BOP. NU wellhead. MOL.

John Hagstorm, BLM representative was on location.
Jim Morris, MVCI representative was on location.