

**RECEIVED**

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

**JAN 05 2012**

Sundry Notices and Reports on Wells

Farmington Field Office  
Bureau of Land Management

1. **Type of Well**  
GAS

5. **Lease Number**  
SF-079514

6. **If Indian, All. or  
Tribe Name**

7. **Unit Agreement Name**  
San Juan 29-7 Unit

2. **Name of Operator**  
**BURLINGTON**  
RESOURCES OIL & GAS COMPANY LP

8. **Well Name & Number**  
San Juan 29-7 Unit 77N

3. **Address & Phone No. of Operator**

PO Box 4289, Farmington, NM 87499 (505) 326-9700

9. **API Well No.**

30-039-30993

4. **Location of Well, Footage, Sec., T, R, M**

Surface: Unit O (SWSE), 1138' FSL & 1522' FEL, Section 33, T29N, R7W, NMPM

BH : Unit J (NESE), 2035' FSL & 531' FEL, Section 33, T29N, R7W, NMPM

10. **Field and Pool**  
Basin DK/Blanco MV

11. **County and State**  
Rio Arriba, NM

**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA****Type of Submission****Type of Action**

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Other - ☐ Cathodic

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Plugging

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Final Abandonment

☐ Altering Casing

☐ Conversion to Injection

**RCVD JAN 11 '12**

**OIL CONS. DIV.**

**13. Describe Proposed or Completed Operations**

Attached is a drawing for the placement of the cathodic ground, rectifier and cable for the subject well.

**DIST. 3**

**ACCEPTED FOR RECORD****JAN 06 2012**

**FARMINGTON FIELD OFFICE**  
BY Denise Journey

**14. I hereby certify that the foregoing is true and correct.**

Signed Denise Journey Denise Journey

Title: Regulatory Technician Date 12/28/11

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

**CONDITION OF APPROVAL, if any:**



Title 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

**NMOCD A**



## San Juan 29-7 #77N

Section 33, T29N, R07W, N.M.P.M., Rio Arriba County, NM



Drill ground bed approximately 110' southwest of #77A wellhead at staked location. Replace rectifier with 4016 three-lug unit and connect to ground bed and #77N wellhead. Reconnect old ground beds, #77A and #514 wellheads. Repair cables as required. This will also require crossing an Enterprise pipeline.

#77N Cables:

Negative: 225'

Positive: 55'

Total Ditch: 280'

By: Scott Smith  
Date: 11/18/2011