



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1/26/2012 Operator DEVON ENERGY API #30-0 45-10589

Property Name NEBU Well No. 59 Location: Unit A Section 24 Township 31 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 114 Intermediate 130 Casing 131 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					<u>130</u>
10 min					<u>129</u>
15 min					<u>129</u>
20 min					<u>129</u>
25 min					<u>128</u>
30 min					<u>129</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	<u>✓</u>
Down to Nothing	
Nothing	<u>✓</u>
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD JAN 27 '12
OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 15

DIST. 3

REMARKS:

NOTHING ON BRADENHEAD WHEN FIRST OPENED, INTERMEDIATE BLEW DOWN TO
SLIGHT GAS ONLY SURGES WITHIN FIRST 5 MIN OF TEST AND CONTINUED SURGING THROUGHOUT TEST

By Phil RYBACK

Witness _____

LEASE OPERATOR Tech
(Position)

E-mail address PHILIP.RYBACK@DEVON.COM