UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

JAN 18 2912

FARMINGTON FIELD OFFICE BY TE Solvers

Sundry Notices and Reports on Wells		Farmington Field Office Bureau of Land Managemen.	
	5.	Lease Number	
	_	SF-081240	
1. Type of Well GAS	6.	If Indian, All. or Tribe Name	
UND		111be Name	
2 N 60	7.	Unit Agreement Name	
2. Name of Operator			
BURLINGTON			
RESOURCES OIL & GAS COMPANY LP	- 8.	Well Name & Number	
3. Address & Phone No. of Operator	0.	HORTON 1B	
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.	
	-	30-045-35252	
4. Location of Well, Footage, Sec., T, R, M			
Surface: Unit I (NE/SE), 1426' FSL & 773' FEL, Section 35, T32N, R11W, NMPM	10.	Field and Pool	
		BLANCO MV / BASIN D BASIN MANCOS	
	11.	County and State	
	-	San Juan, NM	
Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection		RCVD JAN 27'12 OIL CONS. DIV.	
V ⁰ — — — — — — — — — — — — — — — — — — —		DIST. 3	
13. Describe Proposed or Completed Operations 01/03/12 MIRU AWS 730. NU BOPE. PT csg to 600#/30mm @ 16:30hrs on 01/04/12 Test - OK. PU & TIH w/ 8 3/4" ahead to 3735' - Inter TD reached 01/08/12. Circ. hole & RIH w/ 881ts, 7", 23#, J-55, LT&C csg set @ 3712', w/ \$T @ 2bbls FW. Pumped scavenger w/ 19sx(\$7cf-10bbls=3.02yld) Premium Lite w/ 3% CaCl, 0.25 pps celloflake, 5pps LCM-1, 0.4% FL-52, 8% be 21bbls=1.38yld) Type III cnt w/ 1% CaCl, 0.25 pps celloflake, & 0.2% FL-52. Shut dwn Dropped plug & displaced w/ 19.03hrs 01/09/12. Open ST, & Circ. 20bbls cnt to surface. WOC. 2 nd Stage: Preflushed w/ 10bbls of FW, w/ 10bbls 9sx(\$7cf-10bbls=3.02yld) Premium Lite w/ 3% CaCl, 0.25 pps celloflake, 5pps LCM-1, 0.4% FL-52, 8% bentonte, & 153bbls=2.13yld) Premium Lite w/ 3% CaCl, 0.25 pps celloflake, 5pps LCM-1, 0.4% FL-52, 8% bentonte, & 153bbls=2.13yld) Premium Lite w/ 3% CaCl, 0.25 pps celloflake, 5pps LCM-1, 0.4% FL-52, 8% bentonte, & 153bbls=2.13yld) Premium Lite w/ 3% CaCl, 0.25 pps celloflake, 5pps LCM-1, 0.4% FL-52, 8% bentonte, & 0.4% SN 115bbls of FW Bumped Plug & close ST. Plug down @ 21.11hrs. on 01/09/12. Circ. 64bbls cmt to surface. WOC. TIH, & tagged & DO ST @ 2906'. PT 2" csg to 1500#/30min @ 11·30hrs on 01/10/12 Test -OK. Drilled w/ 6 1/4", tag on 01/12/12 Circ hole & RIH w/ 4 1/2", 187jts,(58jts, BTC & 129jts, LT&C) 11.6#, 1_80 csg set @ 7987'. RU to cmt. Pumped scavenger 9sx(28cf-5bbls=3.10yld) Premium lite HS FM, 0.25 pps celloflake, 0.3% CD-32, 6.25pps LCM-1, 107bbls=1.98yld) Premium lite HS FM, 0.25 pps celloflake, 0.3% CD-32, 6.25pps LCM-1 & 1% FL-52. Dropped plug Plug down @ 01·47hrs on 01/14/12 RD cmt. WOC. ND BOPE. NU WH. RD RR @ 08.00hrs on 01/14/12. PT will be conducted by Completion Rig. Results & TOC will appear on next report. 14. I hereby destript that the toregoing is true and correct. Signed Marie E. Jaramillo Title Staff Re	2906' 1s M-1, 0 49 ntonite, & // 40bbls is & 0.4% SM MS. Shut of gged & Do Pre-flush & 1%FL & displa	t Stage: Pre-flushed w/ 10bbls GW, % FL-52, 8% bentonite, & 0.4% SMS to 1.4% S	
APPROVED BY /Title	ACC	EDate FOR RECORD	
CONDITION OF APPROVAL, if any:	Ħ		