District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Biazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office
For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office


Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Appl Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed a	liantia.
Proposed Alternative Method Permit or Closure Plan Appl	
✓ Closure of a pit, closed-loop system, below-grade tank, or proposed✓ Modification to an existing permit	alternative method
Closure plan only submitted for an existing permitted or non-permitted	ted pit, closed-loop system,
below-grade tank, or proposed alternative method	
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-graphers be advised that approval of this request does not relieve the operator of liability should operations result in pollution of sensironment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental au	surface water, ground water or the
Operator	120782
Address PO Box 640 / 721 S Main Aztec, NM 87410	
Facility or well name Rosa Unit 256A	}
API Number:30-039-27652 OCD Permit Number	
U/L or Qtr/Qtr C Section 25 Township 31N Range 6W County	
Center of Proposed Design Latitude 36 87428 Longitude -107 41772	
Surface Owner Federal State Private Tribal Trust or Indian Allotment	
2	
☑ <u>Pit</u> : Subsection F or G of 19 15 17 11 NMAC	RCVD FEB 22 '12
Temporary 🛮 Drilling 🖾 Workover	
☐ Permanent ☐ Emergency ☐ Cavitation ☐ P&A	OIL COMS. DIV.
☐ Lined ☐ Unlined Liner type Thickness <u>20</u> mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other	DIST. 2
⊠ String-Reinforced	
Liner Seams 🛮 Welded 🖾 Factory 🗌 Other Volume 15,714_bbl Dimensions Get from	om Plats L <u>140'</u> x W <u>55'</u> x D <u>12'</u>
3	
Closed-loop System: Subsection H of 19 15 17 11 NMAC	
Type of Operation P&A Drilling a new well Workover or Drilling (Applies to activities which require printent)	or approval of a permit or notice of
☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other	
☐ Lined ☐ Unlined Liner type Thicknessmil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other	
Liner Seams	
1	
Below-grade tank: Subsection I of 19 15 17 11 NMAC	
Volumebbl Type of fluid	
Tank Construction material	
☐ Secondary containment with leak detection ☐ Visible sidewalls, liner, 6-inch lift and automatic overflow shut-or	off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other	
Liner type Thicknessmil	
5	
Alternative Method:	
Submittal of an exception request is required Exceptions must be submitted to the Santa Fe Environmental Bureau of	ffice for consideration of approval

Fencing: Subsection D of 19 15 17 11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)				
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church)				
☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet				
☐ Alternate Please specify As per BLM specifications				
Notting: Subsection F of 10.15.17.11 NIMAC (Applies to new year)				
Netting: Subsection E of 19 15 17 11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other				
Monthly inspections (If netting or screening is not physically feasible)				
8				
Signs: Subsection C of 19 15 17 11 NMAC				
☐ 12"x 24". 2" lettering. providing Operator's name, site location, and emergency telephone numbers ☐ Signed in compliance with 19 15 3 103 NMAC				
Signed in compliance with 1943 3 103 NMIAC	··			
Administrative Approvals and Exceptions:				
Justifications and/or demonstrations of equivalency are required Please refer to 19 15 17 NMAC for guidance Please check a box if one or more of the following is requested, if not leave blank:				
Administrative approval(s) Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau of	office for			
consideration of approval Exception(s) Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval				
Siting Criteria (regarding permitting): 19 15 17 10 NMAC				
Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accep				
material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appro office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a				
Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dryi above-grade tanks associated with a closed-loop system.	ng pads or			
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank	☐ Yes 🛛 No			
- NM Office of the State Engineer - IWATERS database search, USGS, Data obtained from nearby wells	□ Vaa □ Na			
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	☐ Yes ☑ No			
- Topographic map, Visual inspection (certification) of the proposed site				
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to temporary, emergency, or cavitation pits and below-grade tanks)	☐ Yes ☑ No ☐ NA			
- Visual inspection (certification) of the proposed site, Aerial photo, Satellite image				
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to permanent pits)	☐ Yes ☐ No 図 NA			
- Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	□ v □ v-			
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application - NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site	☐ Yes ⊠ No			
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes 🖾 No			
adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approval obtained from the municipality				
Within 500 feet of a wetland	☐ Yes ☑ No			
- US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site				
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes 🖾 No			
Within an unstable area	☐ Yes ⊠ No			
 Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources, USGS, NM Geological Society, Topographic map 				
Within a 100-year floodplain - FEMA map	☐ Yes ⊠ No			

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are
attached. ☐ Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19 15 17 9 NMAC ☐ Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15 17 9 NMAC ☐ Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC ☐ Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC ☐ Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC ☐ Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Previously Approved Design (attach copy of design) API Number or Permit Number
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 1915 179 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Previously Approved Design (attach copy of design) API Number
Previously Approved Operating and Maintenance Plan API Number(Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19 15 17 9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19 15 17 11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19 15 17 11 NMAC Leak Detection Design - based upon the appropriate requirements of 19 15 17 11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19 15 17 11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Proposed Closure: 19 15 17 13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type
Waste Excavation and Removal Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Instructions: Please identify the facility or facilities for the disposal of liquids, difacilities are required.	Steel Tanks or Haul-off Bins Only: (19 15 17 13 I rilling fluids and drill cuttings. Use attachment if m	O NMAC) ore than two		
	Disposal Facility Permit Number	·		
	Disposal Facility Permit Number			
Will any of the proposed closed-loop system operations and associated activities of Yes (If yes, please provide the information below) No	-			
Required for impacted areas which will not be used for future service and operatio Soil Backfill and Covei Design Specifications based upon the appropriate Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection	requirements of Subsection H of 19 15 17 13 NMA(I of 19 15 17 13 NMAC	С		
Siting Criteria (regarding on-site closure methods only): 19 15 17 10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the provided below. Requests regarding changes to certain siting criteria may require considered an exception which must be submitted to the Santa Fe Environmental demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC J	e administrative approval from the appropriate disti Bureau office for consideration of approval. Justi	rict office or may be		
Ground water is less than 50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS, Data	a obtained from nearby wells	☐ Yes ☒ No ☐ NA		
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS, Data	a obtained from nearby wells	☐ Yes ☑ No ☐ NA		
Ground water is more than 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS, Data	a obtained from nearby wells	⊠ Yes □ No □ NA		
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other sig lake (measured from the ordinary high-water mark) - Topographic map, Visual inspection (certification) of the proposed site	nificant watercourse or lakebed, sinkhole, or playa	☐ Yes ⊠ No		
Within 300 feet from a permanent residence, school, hospital, institution, or church - Visual inspection (certification) of the proposed site, Aerial photo, Satellite		☐ Yes ☑ No		
Within 500 horizontal feet of a private, domestic fresh water well or spring that less watering purposes, or within 1000 horizontal feet of any other fresh water well or s - NM Office of the State Engineer - iWATERS database, Visual inspection (pring, in existence at the time of initial application	☐ Yes ☑ No		
Within incorporated municipal boundaries or within a defined municipal fresh water adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approve	•	☐ Yes ⊠ No		
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map, Visua	al inspection (certification) of the proposed site	☐ Yes ⊠ No		
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining	and Mineral Division	☐ Yes ☑ No		
Within an unstable area - Engineering measures incorporated into the design, NM Bureau of Geology Society, Topographic map	y & Mineral Resources, USGS, NM Geological	☐ Yes ☑ No		
Within a 100-year floodplain - FEMA map		☐ Yes ⊠ No		
On-Site Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19 15 17 11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19 15 17 11 NMAC Protocols and Procedures - based upon the appropriate requirements of 19 15.17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved) Soil Cover Design - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC				

Operator Application Certification:
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief
Name (Print) Title
Signature Date
e-mail address Telephone
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment) OCD Representative Signature: Approval Date: 1/23/2012 Title: OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 19 15 17 13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.
☐ Closure Completion Date: 12/9/2011
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.
Disposal Facility Name Disposal Facility Permit Number
Disposal Facility Name Disposal Facility Permit Number
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate compliance to the items below) No
Required for impacted areas which will not be used for future service and operations Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location Latitude 36 87428 Longitude 107 41772 NAD 1927 1983
Operator Application Certification:
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief
Name (Print) Ben Mitchell Title Regulatory Specialist
Signature: R WHA Date 2/1/2012
c_mail address hen mitchell@wnvenergy.com Telephone 505_333_1806



Williams Production Co., LLC San Juan Basin: New Mexico Assets

Temporary Pit In-place Closure Report Drilling/Completion and Workover (Groundwater >100 feet bgs)

Well: (Rosa Unit #256A)
API No: 30-039-27652

Location: C-25-T31N-R06W, NMPM

In accordance with Rule 19 15 17 13 NMAC, the following plan describes the general in-place closure requirements of temporary pits on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard procedure for all temporary pits to be utilized for the drilling, completion and/or workovers of oil and gas wells operated by WPX. For those temporary pits which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the pit closure on a Closure Report using Division Form C-144 The Report will include the following:

- Details on Capping and Covering, where applicable
- Plot Plan (Pit Diagram)
- Inspection reports
- Sampling Results
- Division Form C-105. WELL COMPLETION OR RECOMPLETION REPORT AND LOG
- Copy of Deed Notice filed with the County Clerk (format to meet County requirements)
 <u>A deed notice is not required on state, federal or tribal land according to NMOCD FAQ dated October 30</u>, 2008 and posted on the NMOCD website

General Plan Requirements

All free standing liquids will be removed from the pit at the start of the closure process. Liquids will be removed in a manner that the appropriate District Office approves including; recycled, reused, reclaimed, evaporated, and/or disposed of in a Division-approved facility. Once all free liquids are removed, the sludge will be stabilized by one of the following methods depending on equipment availability. blending with clean stockpiled soils or dewatering using a Bowl Decanter Centrifuge then blending with clean stockpiles soils.

To the extent practical, free liquids were pulled from the reserve pit following the completion rigoff Haul dates were from (12/2/2011 to #002 API # 30-039-3081 Order – SWD-1236)

- 2. The preferred method of closure for all temporary pits will be on-site closure by in-place burial, provided all the criteria in 19.15 17 13 B are met

 On-site burial plan for this location was approved by the Aztec District Office on (10/06/11)
- 3 The surface owner shall be notified of WPX's proposed closure plan using a means that provides proof of notice (i.e. certified mail/return receipt requested)

 Williams notified the SMA of its intent to use a temporary pit and onsite burial in the Surface Use

 Plan in the well APD. The SMA was notified by email see attached. No return receipt required per BLM FFO/NMOCD MOU dated 5/4/09
- 4 Within six months of the "rig-off" status occurring WPX will ensure that the temporary pit is covered, recontoured and reseeding in progress

 <u>Drill rig-off 11/8/2011 Completion rig-off 11/28/2011 Pit covered 12/9/2011. Pit area along with unused portions of well pad to be interim reclaimed in accordance with Surface Management Agency requirements in APD-COAs and per BLM FFO/NMOCD MOU dated 5/4/09</u>
- 5 Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following
 - a Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)

<u>The Aztec District Office of NMOCD was notified by email using a format acceptable to the District Copies of the notification from Abode Contractors on 12/1/2011</u> is attached.

6. The pit liner shall be removed above "mud level" after stabilization. Removal of the liner will consist of manually or mechanically cutting the liner at the mud level and removing all remaining liner. Care will be taken to remove "all" of the liner (I e anchored material). All excessive liner will be disposed of at a licensed disposal facility (probably San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426).

The liner to the temporary pit was removed above the "mud level" once stabilized Removal of the liner consisted of manually cutting the liner and removing all remaining liner material above the "mud level" including the anchor material. All excessive liner was disposed of at the San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426

7. Solidification of the remaining pit contents shall be achieved by mixing non-waste containing, earther material. The solidification process will be accomplished use a combination of natural drying and mechanical mixing. Pit contents will be mixed with non-waste, earther material to a consistency that is deemed safe and stable. The mixing ratio shall not exceed 3 parts non-waste to 1 part pit contents.

Following removal of free liquids, the pit contents were mixed with non-waste containing, earthen material in order to achieve appropriate solidification and a consistency that was deemed safe and stable. The solidification process was accomplished using a combination of natural drying, and mechanically mixing using a dozer and trackhoe. The mixing ration was approximately 2.5-3 parts native soil to 1 part pit contents. Solidification was completed 12/7/2011

8. A five-point composite sample will be taken of the pit using sampling tools and all samples tested per 19.15.17 13(B)(1)(b) NMAC. In the event that the criteria are not met (See Table 1), all contents will be handled per 19.15.17 13(B)(1)(a) (i.e. dig and haul to a Division-approved facility). Approval to haul will be requested of the Aztec District office prior to initiation.

A five-point composite sampling was taken of the pit area using sampling tools and the sample was tested per 19.15 17 13(B)(1)(b) NMAC. Results are shown in Table 1 and lab reports are attached.

Table 1: Closure Criteria for Temporary Pits in Non-sensitive Areas with Groundwater >100 bgs

Components_	Testing Methods	Limits (mg/Kg)	Pit (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	02	ND
BTEX	EPA SW-846 Method 8021B or 8260B	50	0076
TPH	EPA SW-846 Method 418 1	2500	25 7
GRO/DRO	EPA SW-846 Method 8015M (GRO/DRO)	500	ND
Chlorides	EPA SW-846 Method 300.1	500	200

9 Upon completion of solidification and testing, the pit area will be backfilled with non-waste earthen material compacted to native conditions to enable effective revegetation for successful evapotranspiration. A minimum of four feet of cover including replacement of one foot of suitable material to establish vegetation, or the background thickness of topsoil, whichever is greater.

<u>Upon completion of solidification and testing, the pit area was backfilled with non-waste earthen</u> <u>material compacted to native conditions</u>. A minimum of four feet of cover to the extent <u>practical</u> was achieved and the cover included just over a foot of topsoil suitable to <u>establish vegetation</u>.

10 Following cover, the site will be recontoured to meet the Surface Management Agency or surface owner requirements Re-contouring will attempt to match fit, shape, line form, and texture of the surrounding geography Re-shaping will include drainage control, prevent ponding, and minimize erosion. Natural drainages will be unimpeded and stormwater Best Management Practices (BMPs) will be used to aid in soil stabilization and protection surface water quality

Following cover, Williams reestablished drainage and contours to approximately match previous topography meeting the Conditions of Approval in the APD and the direction offered by a BLM/USFS inspector. Cover and re-contouring were completed 12/9/2011

- 11. Notification will be sent to the Aztec District office when the reclaimed area is seeded Williams will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM FFO/NMOCD MOU dated 5/4/09.
- 12 WPX shall seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth.

Page 8 of 9 Rosa Unit 256A

occurs Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) or Land owner as part of a surface use agreement or APD are Division-approved methods unless notified by the Division of their unacceptability.

Williams will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM FFO/NMOCD MOU dated 5/4/09.

13 The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the on site burial upon the abandonment of all wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the on site burial of the temporary pit. The plate will be easily removable and a four-foot tall riser will be threaded into the top of the collar marker and welded around the base with the operations information at the time of all wells on the pad abandoned. The information will include Operator Name, Lease Name, Well Name, and number, USTR, and an indicator that the marker is an onsite pit burial location.

The temporary pit was located with a steel marker meeting the above listed specifications. The marker has the following information welded for future reference: Williams Production, C-25-T31N-R05W-C, "In Place Burial" (photo attached). Steel marker set 12/14/2011

Page 9 of 9 Rosa Un.t 256A



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	W.P.X	Project #:	04108-0136
Sample ID:	Reserve Pit	Date Reported:	12-13-11
Laboratory Number:	60580	Date Sampled:	12-09-11
Chain of Custody No:	13049	Date Received:	12-09-11
Sample Matrix:	Soil	Date Extracted:	12-12-11
Preservative:	Cool	Date Analyzed:	12-13-11
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid

Waste, SW-846, USEPA, December 1996.

Comments:

Rosa Unit 256A

Analyst

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc com envirotech-inc com



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC	Project #:	N/A
Sample ID:	12-13-11 QA/QC	Date Reported:	12-13-11
Laboratory Number:	60580	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	12-13-11
Condition:	N/A	Analysis Requested:	TPH

	I-Cal Date	Ji-Call RF.	C-CallRF %	Difference	Accept Range
Gasoline Range C5 - C10	40890	9 996E+02	1.000E+03	0.04%	0 - 15%
Diesel Range C10 - C28	40890	9.996E+02	1.000E+03	0.04%	0 - 15%

Blank Conc. (mg/L-mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	0.5	0.2
Diesel Range C10 - C28	0.1	0.1

Duplicate Conc. (mg/Kg)	Sample	Duplicate	2% Difference	Range
Gasoline Range C5 - C10	ND	ND	0.00%	0 - 30%
Diesel Range C10 - C28	ND	ND	0.00%	0 - 30%

Spike Conc. (mg/Kg)	"Sample	Spike Added	Spike Result	% Recovery	Accept: Range
Gasoline Range C5 - C10	ND	250	241	96.2%	75 - 125%
Diesel Range C10 - C28	ND	250	286	115%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid

Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 60577-60580 and 60587

Analyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	W.P.X.		Project #:		04108-0136
Sample ID:	Reserve Pit		Date Reported:		12-13-11
Laboratory Number:	60580		Date Sampled:		12-09-11
Chain of Custody:	13049		Date Received:		12-09-11
Sample Matrix:	Soil		Date Analyzed.		12-13-11
Preservative:	Cool		Date Extracted:		12-12-11
Condition:	Intact		Analysis Requested:		BTEX
			Dilution:		10
		Concentration		Det. Limit	
Parameter		(ug/Kg)		(ug/Kg)	
Benzene		ND		0.9	
Toluene		2.0		1.0	
Ethylbenzene		1.1		1.0	
p,m-Xylene		2.5		1.2	
o-Xylene		2.0		0.9	
Total BTEX					

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	87.9 %
	1,4-difluorobenzene	96.0 %
	Bromochlorobenzene	99.7 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996

Comments:

Rosa Unit 256A

Analyst

Review



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

0.9

Client ⁻	N/A	1	Project #:	N _i	/ A		
Sample ID [.]	1213BBLK QA/QC	ŧ	Date Reported:	12	12-13-11		
Laboratory Number:	60587	ı	Date Sampled:	N	/A		
Sample Matrix:	Soil	ı	Date Received:	N	/A		
Preservative.	N/A	(Date Analyzed:	12	2-13-11		
Condition:	N/A		Analysis:	В.	TEX		
	Dilution.						
Calibration and	ol-Cal RF:	C-Cal RF	%Diff:	Blank	Detect.		
Detection Limits (ug/L)		Accept Rang		Concl	Limit:		
Landenser strategisteristration and the Set of American	ilan and a said and a said and a said a	بالمنتقة المتناف المتناه المتناه					
Benzene	2 2714E+007	2.2760E+007	0.2%	ND	0.1		
Toluene	2.3016E+007	2 3063E+007	0.2%	ND	0.1		
Ethylbenzene	2 0329E+007	2 0370E+007	0.2%	ND	0.1		
p,m-Xylene	5.0841E+007	5 0943E+007	0.2%	ND	0.1		
o-Xylene	1.8866E+007	1 8904E+007	0.2%	ND	0.1		
Duplicate Conc. (ug/Kg):	K. (∴.) Sample ,∜∴	∴ Duplicate	iq ₹%Diff! ∴	Accept Range	Detect Limit		
Benzene	ND	ND	0.0%	0 - 30%	0.9		
Toluene	1.3	1.3	0.0%	0 - 30%	1.0		
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0		
p,m-Xylene	3.9	3.8	2.6%	0 - 30%	1.2		

Spike Conc# (ug/Kg) Sample Amount Spiked Spiked Sample Recovery Accept Range												
Benzene	ND	500	479	95.8%	39 - 150							
Toluene	1.3	500	469	93.6%	46 - 148							
Ethylbenzene	ND	500	473	94.6%	32 - 160							
p,m-Xylene	3.9	1000	954	95.0%	46 - 148							
o-Xylene	2.4	500	478	95.2%	46 - 148							

2.4

0.0%

0 - 30%

2.4

ND - Parameter not detected at the stated detection limit.

Dilution: Spike and spiked sample concentration represent a dilution proportional to sample dilution.

References¹

o-Xylene

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 60577-60580 and 60587

Analyst



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	W.P.X.	Project #:	04108-0136
Sample ID:	Reserve Pit	Date Reported:	12-12-11
Laboratory Number:	60580	Date Sampled:	12-09-11
Chain of Custody No:	13049	Date Received:	12-09-11
Sample Matrix:	Soil	Date Extracted:	12-12-11
Preservative:	Cool	Date Analyzed:	12-12-11
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

25.7

6.4

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Rosa Unit 256A

Analyst

RAHIOW

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc com envirotech-inc com



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS QUALITY ASSURANCE REPORT

Client:

QA/QC

Project #.

N/A

Sample ID:

QA/QC

Date Reported:

12-12-11

Laboratory Number:

12-12-TPH.QA/QC 60577

12-12-11

Date Sampled:

N/A

Sample Matrix: Preservative:

Freon-113 N/A

Date Analyzed: Date Extracted: 12-12-11 12-12-11

Condition:

N/A

Analysis Needed:

TPH

Calibration

C-Cal Date I-Cal Date

11-16-11

LCal RE

1,610

C-Cal RF: % Difference Accept. Range 1.720

6.8%

⊹/- 10%

Blank Conc. (mg/kg)

Concentration

Detection Limit

TPH

TPH

TPH

ND

6.4

Duplicate Conc. (mg/Kg)

Sample :: " 19.3

Duplicate: % Difference Accept Range 19.3

0.0%

÷/- 30%

Spike Conc. (mg/Kg)

19.3

Spike Added Spike Result % Recovery Accept Range 2,000

1,670

82.7%

80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 60497 and 60573-60580

Analyst

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865

lab@envirotech-inc.com envirotech-inc.com



Chloride

Client: Sample ID: W.P.X.

Project #:

04108-0136

Reserve Pit

Date Reported:

12-13-11

Lab ID#: Sample Matrix: 60580 Soil

Date Sampled: Date Received: 12-09-11

Preservative:

Cool

Date Analyzed:

12-09-11 12-13-11

Condition:

Intact

Chain of Custody:

13049

Parameter

Concentration (mg/Kg)

Total Chloride

200

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Rosa Unit 256A

Analyst

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc com envirotech-inc com

13049

CHAIN OF CUSTODY RECORD

Client: W.P.X.		Pro	Rosa Un, t	ion: 25	6 A				ANALYSIS / PARAMETERS													
Email results to:		Sa	mpler Name:	,	Shu	16/	/		8015)	1 8021)	8260)	S				-						
Client Phone No.: Mybe Lane	2		ent No.: 04108	-01	36				TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P	CO Table 910-1	TPH (418.1)	CHLORIDE			le Cool	Sample Intact
Sample No./ Identification	Sample Date	Sample Time	Lab No.		/Volume ontainers	P HgCl ₂	reserval HCI	tive	TPH (BTEX	, Voc	RCR/	Catio	RCI	TCLP	00	TPH	몽			Sample	Samp
Reserve Pit	179/11	1:35	60580	1	402				V	i/							V				y	y
																				_		
																					_	
Relinquished by: (Signature)	110	1		Date 12/5/	Time Zoo	Recei	ved b	y: (Si	gnatu	ire)	m		<u> </u>	1.		1				Date 129-1	1	me >00
Relinquished by: (Signature)						Recei				ire)		-						٠				
Sample Matrix Soil Solid Sludge	Aqueous 🗌	Other 🗌															•					
☐ Sample(s) dropped off after	hours to sec	cure drop off	area.	3	P N V Anal	Î [€) [(e C) itory)								-		_		
5795 US Highway 64	• Farmingto	on, NM 8740	I • 505-632-0615 • T	hree Spri	ings • 65 N	/ercac	io Stre	et, Su	iite I 1	15, Du	ırang	o, C0	8130	D1 • F	abore	atory	@env	virote	ch-inc.	com		

District I 1625 N French Drive, Hobbs, NM 88240 Phone.(575) 393–6161 Fax:(575) 393–0720

District II 811 S First Street, Artesia, NM 88210 Phone (575) 748–1283 Fax: (575) 748–9720

District III 1000 Rio Brazos Road, Aztec, NM 87410 Phone (505) 334-6178 Fax: (505) 334-6170

District IV 1220 S St. Francis Drive, Santa Fe, NM 87505 Phone (505) 476-3460 Fax: (505) 476-3462

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised August 1, 2011

Submit one copy to Appropriate District Office

OIL CONSERVATION DIVISION 1220 South St. Francis Drive Santa Fe, NM 87505

AMENDED REPORT

MELL	V VID	V CDE V CE	DEDICATION	

'API Number	*Pool Code 71629	3Pool Name BASIN FRUITLAND COAL							
Property Code 17033	•	perty Name SA UNIT	*Well Number 256A						
'OGRID No	*Oper	rator Name	*Elevation						
120782	120782 WILLIAMS PRODUCTION COMPANY								
	10 Cup fo	ce Location							


Surface Location

UL or lot no	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County			
С	25	31N	6W		1302	NORTH	1586	WEST	RIO ARRIBA			
11 Bottom Hola Location If Different From Sunface												

Bottom Hole Location It Different From Surface

UL or lot no	Section 25	Township 31N	Range 6W	Lot Idn	Feet from the	North/South line NORTH	Feet from the	East/West line EAST	County RIO ARRIBA
¹² Dedicated Acres	278	2.16 Acr	res – N	1/2	13 Joint or Infill	¹⁴ Consolidation Code	¹⁵ Onder No		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



17 OPERATO I hereby certify herein is true as knowledge and be either owns a wo mineral interest proposed bottom- to drill this we to a contract wi or working intere agreement or a c heretofore entere	that the nd complet lief, and rking into in the la noile location an ownest, or to compulsory	informate to that the erest of and included incl	ation conta: he best of is organiza r unleased luding the has a righ lon pursuani uch a miner ntary pooli g order	ined my tion
Signature		Da	te	
Printed Name				
E-mail Address	************			
I hereby certif shown on this i notes of actual my supervision, and correct to Date Revise Survey Dat	ty that the plat was in surveys and that the best ed: NOVE	we well clotted made by the sa of my EMBER	location from field me or und me is true belief 3 30, 20 25, 200	11 03
Signature and S			•	r
	ME ME 1526	٠)	1 1 1	
Tagger	<u></u>	É.	31.44 DO	_
<u>UASUN</u>	<u>၂</u> .		JWAHL	5
Certificat	te Numb	er	15269	

Meador, Tasha

From: johnny@adobecontractorsinc.com

Sent: Thursday, December 01, 2011 12:24 PM

To: bliess@blm.gov; mkelly@blm gov; rmckee@blm.gov; rswitzer@blm.gov

Cc: Meador, Tasha; Granillo, Lacey
Subject: Williams Clean ups Rosa Unit #256A

We will be ready to start the clean up on the Rosa Unit #256A on Monday or Tuesday of next week Please let me know if you have any questions.

Thank you,

Johnny Stinson Gen. Manager/ Adobe Contractors Office: (505)632-1486

Mobile. (505)320-6076

johnny@adobecontractorsinc com

Meador, Tasha

From: johnny@adobecontractorsinc.com

Sent: Thursday, December 01, 2011 12:22 PM

To: Brandon Powell

Cc: Meador, Tasha; Granıllo, Lacey; Lepich, Mark, glenn@adobecontractorsinc.com

Subject: Williams Clean ups Rosa Unit #256A

Brandon,

We will be ready to start the clean up on the Rosa Unit #256A on Monday or Tuesday of next week Please let me know if you have any questions.

Thank you,

Johnny Stinson
Gen Manager/ Adobe Contractors

Office: (505)632-1486 Mobile. (505)320-6076

johnny@adobecontractorsinc.com

Submit To Appropriate Two Copies District I 1625 N French Dr			State of New Mexico Energy, Minerals and Natural Resources						Form C-105 July 17, 2008 1 WELL API NO!							
District II 1301 W Grand Ave District III 1000 Rio Brazos Re District IV	enue Artesia d Aztec NM	NM 88210 87410	Oil Conservation Division 1220 South St. Francis Dr.						30-039-27652 2							
1220 S St Trancis Dr Santa Fe, NM 87505 Santa Fe, NM 87505									3 State Oil & Gas Lease No SF-078766 5 Lease Name of Unit Agreement Name							
☐ COMPLET									d #32 and/o	01	6 Well Numb			osa 		
#33, attach this a 7 [Type of Comp NEW	nd the plat to pletion WELL	o the C-144 clo	sure report i	n accord	ance with 19 I	15 17	3 K NI	MAC)			✓ OTHER 9 OGRID	Side	-Track_			
8 Name of Operator WPX Energy Production, LLC 10 Address of Operator PO BOX 640 AZTEC, NM 87410									11 Pool name							
12 Location Surface:	Unit Lti	Section	Townsh	пр	Range	Lot		F	eet from th	ne l	N/S Line	Feet from the		E/W L	Line	County
BH: 13 Date Spudded		eTD Reached	15 D.	ate Rig F	Released 11/28/2011			16 D.	ate Comple	eted	(Ready to Prod	uce)		Elevat , GR, e		and RKB,
18 Total Measur 22 Producing In					Measured De	pth		20 W	/as Directi	ona	Survey Made ⁹		21 Турс	Electri	c and Ot	her Logs Run
23 CASING SI	ZE	WEIGHT LE			NG REC	OR			t all str	ing	gs set in wo		CORD	AN	10UNT	PULLED
24 SIZE	ТОР	В	ОТТОМ		R RECORD SACKS CEM	IENT	SCR	EEN		25 SIZ			NG RECO	ORD	PACKI	ER SET
26 Perforation									, SHOT, I	FR	RACTURE, CEMENT, SQUEEZE, ETC AMOUNT AND KIND MATERIAL USED					
28						DD	ODU	CT	ION							
Date First Produc	etion	Produ	iction Meth	od (Flou	ring gas lift p					•	Well Status	(Proc	or Shut-	n)		
Date of Test	Hours T		Choke Size	•	Prod'n For Test Perrod		Oıl -				- MCF	W	ater - Bbl			Dil Ratio
Flow Tubing Press 29 Disposition of		ŀ	Calculated 24 Hour Rate	4-	Oıl - Bbl	-		Gas - M 	1CF		Water - Bbl	30 T	Oil Grav		PI - (Cor:	r)
31 List Attachm		used for fact 1											est Withe			
32 If a temporar	y pit was us	ed at the well, a	ttach a plat	with the	location of the	temp	otary p	<u>it</u> ;								
33 If an on-site	burial was u	sed at the well,	report the ex	ract local				naitude	e -107 417	772			NΔ	D#1983		
I hereby certing B Signature	fy that the	e information	shown of Printed N		sides of this	s forn	is tri	ue an	d comple	ete	to the best o		<u>knowled</u>	ge and		
E-mail Addre	ess: ben n	ntchell@wp	xenergy c	<u>om</u>			itic	negi	aratory 5	.pcc	Janot Dall	, <u> </u>				



TEMPORARY PIT INSPECTION REPORT

Well Name		Rosa Unit 256A		Field Name	Ba	sin Fruitland Coal		API#		30-039-27652	Report #	1
Location	NE/4 NW/4 Sec 25(C), T31N,		31N, R6W	County		State		NM	Rpt Date	6/25/2011		
Date	Report Type	Inspector	Liner Intact Y/N	Fenced Y/N	Slopes Intact Y/N	Adequate Freeboard Y/N	Oil Free Y/N	Flare Pit Liquid Free Y/N		Comment		
10/28/11	Daily		Υ	Y	Υ	Υ	Υ	Υ				
10/29/11	Daily		Y	Υ	Υ	Y	Y	\	1	<u></u>		
10/30/11	Daily		Y	Y	Υ	Υ	Y	\	′			
10/31/11	Daily		Υ	Υ	Υ	Υ	Υ	١	1			
11/1/11	Daily		Υ	Υ	Y	Υ	Y)	1			
11/2/11	Daily		Υ	Υ	Y	Υ	Y	\\	1			
11/3/11	Daily		Υ	Υ	Υ	Υ	Υ	`	1			
11/4/11	Daily		Υ	Υ	Υ	Υ	Υ	\	′		•	
11/5/11	Daily		Υ	Υ	Y	Υ	Y	,	7			
11/6/11	Daily		Υ	Υ	Υ	Υ	Υ	١	1			
11/7/11	Daily		Υ	Υ	Υ	Υ	Υ	١	1			
11/8/11	Daily		Y	Υ	Υ	Υ	Υ	١	1			
11/12/11	Daily		Υ	Υ	Υ	Υ	Υ	١	1			
11/13/11	Daily		Υ	Υ	Υ	Υ	Υ	`	1			
11/14/11	Daily		Υ	Υ	Υ	Υ	Υ	\	1			
11/15/11	Daily		Υ	Y	Υ	Υ	Y	,	1			
11/16/11	Daily		Υ	Υ	Υ	Υ	Y	1				
11/17/11	Daily		Υ	Υ	Υ	Υ	Y	,	′			_
11/18/11	Daily		Υ	Υ	Y	Υ	Y	١	1			
11/19/11	Daily		Y	Υ	Y	Y	Υ	`	1			
11/20/11	Daily		Υ	Υ	Y	Y	Υ	1	1			
11/21/11	Daily		Y	Υ	Y	Y	Υ	,	1			
11/22/11	Daily		Y	Υ	Y	Υ	Υ	,	1			

2001-2009 WellEz Information Management, LLC All rights reserved ver 111709jc

