



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emmr.state.nm.us/ocd/DistrictIII/District.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 3/22/05 Operator Coult H. RAST, MNG API #30-0 43-05035

Property Name Darla Well No. 2 Location: Unit H Section 33 Township 18^N Range 3^W

Well Status(Shut-In or Producing) Tubing NO Intermediate NO Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>0</u>	Steady Flow	
10 minutes		<u>0</u>	Surges	
15 minutes		<u>0</u>	Down to Nothing	
20 minutes		<u>0</u>	Nothing <u>X</u>	
25 minutes		<u>0</u>	Gas	
30 minutes		<u>0</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By Ramon J. Lopez
Rig operator
(Position)

Witness _____

