

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-31951

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact Kristina Kovach
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-326-9866
Facility Name Howell D #351S	Facility Type Gas Well
Surface Owner Federal	Lease No. NM SF-078387
Mineral Owner Federal	API # 30-045-31951

LOCATION OF RELEASE

Unit Letter F	Section 29	Township T31N	Range R8W	Feet from the 1490'	North/South Line North	Feet from the 1620'	East/West Line West	County San Juan
-------------------------	----------------------	-------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

Latitude **36.87211° N** Longitude **107.70196° W**



NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - 5 BBL	Volume Recovered - 5 BBL
Source of Release: Tank overflow	Date and Hour of Occurrence	Date and Hour of Discovery 3/18/08 - 11:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour -	RCVD APR 2 '08
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	OIL CONS. DIV.
If a Watercourse was Impacted, Describe Fully.*		DIST. 3

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company employee discovered a produced water spill of approximately 5 BBL at the Howell D #351S on the morning of 3/18/08. The spill was caused by a tank overflow that resulted from unexpected increased production at the site. The well was shut in upon discovery.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids were contained within the berm, and all were recovered by vacuum truck. All fluids were pulled from the pit tank. COPC will closely monitor tank levels to prevent reoccurrence.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach	Approved by District Supervisor: 	
Title: Environmental Associate	Approval Date: 2/27/2012	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/24/08 Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

nJK1205836737