District I 1625 N Frénch Dr., Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr., Santa Fe NM 87505

# State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office
For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office

2695	3
QU	

# <u>Pit, Closed-Loop System, Below-Grade Tank, or</u> <u>Proposed Alternative Method Permit or Closure Plan Application</u>

		☐ Closure of Modification	of a pit, closed ition to an exis	-loop syste ting permi	em, below- it	grade tan	ık, or propose	d alternative method ed alternative method nitted pit, closed-loop system,
					dual pit, clos	sed-loop s	ystem, below-g	grade tank or alternative request
								of surface water, ground water or the authority's rules, regulations or ordinances
								120782
Address	PO Box 640	/ 721 S Main	Aztec	<u>, NM 8741</u>	0			
Facility or well name	Rosa Uni	it 339A						
API Number <u>30-04</u>	5-31762		OCD Permit	Number				
U/L or Qtr/Qtr <u>I</u>	Sect	ion <u>32</u>	Township _	<u>32N</u>	Range _	<u>6W</u>	County _	SAN JUAN
Center of Proposed I	Design Latitudo	36	93288	Lo	ngıtude		107 47696	NAD □1927 ⊠ 1983
Surface Owner 🛛 F	ederal   State	Private 7	Гrībal Trust or Iī	ndıan Allotı	ment			
Pit: Subsection Temporary ☑ Dril								RCVD MAR 1'12 OIL CONS. DIV.
Permanent En	nergency 🔲 Ca	vitation 🔲 P&	kΑ					DIST. 3
□ Unline     □ Unline	ed Liner type	Thickness	<u>20</u> mıl ⊠	LLDPE	] HDPE [	PVC 🗆	Other	
String-Reinforced	i							•
Liner Seams   Wo	elded 🛚 Factor	y 🗌 Other _		Vol	lume <u>15,71</u> 4	4_bbl Dı	mensions Get	from Plats L <u>140</u> ° x W <u>55</u> ° x D <u>12</u> °
intent)  Drying Pad	P&A Dri Above Ground	Illing a new wel Steel Tanks   Thickness	l □ Workover  ] Haul-off Binsmil	☐ Other _	E ☐ HDPE	<u>.</u>	_	prior approval of a permit or notice of
4 Below-grade tan	k: Subsection	I of 19 15 17 1	1 NMAC					
Volume	b	bl Type of flu	ıd					
Volumebbl Type of fluid  Tank Construction material								
☐ Secondary conta	inment with leal	k detection	Visible sidewal	lls, liner, 6-	ınch lift and	automati	c overflow shu	t-off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other								
Liner type Thickness	SS	mıl	☐ HDPE ☐ P	vc 🗆 o	ther			
5 Alternative Met Submittal of an exce		required. Exce	eptions must be s	submitted to	o the Santa F	e Enviror	nmental Bureau	a office for consideration of approval


Page 1 of 9 Rosa Unit 339A

<u> </u>									
Fencing: Subsection D of 19 15 17 11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)									
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital institution or church)									
Four foot height, four strands of barbed wire evenly spaced between one and four feet									
Alternate Please specify As per BLM specifications									
7									
Netting: Subsection E of 19 15 17 11 NMAC (Applies to permanent pits and permanent open top tanks)									
Screen Netting Other									
Monthly inspections (If netting or screening is not physically feasible)									
8 Signs: Subsection C of 19 15 17 11 NMAC									
☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers									
Signed in compliance with 19 15 3 103 NMAC									
Administrative Approvals and Exceptions:									
Justifications and/or demonstrations of equivalency are required Please refer to 19 15 17 NMAC for guidance  Please check a box if one or more of the following is requested, if not leave blank:									
Administrative approval(s) Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau of	office for								
consideration of approval  Exception(s) Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval									
Siting Criteria (regarding permitting): 19 15 17 10 NMAC									
Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accep									
material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appro- office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a									
Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dryi									
above-grade tanks associated with a closed-loop system.	☐ Yes ⊠ No								
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank - NM Office of the State Engineer - iWATERS database search, USGS, Data obtained from nearby wells									
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	☐ Yes ☒ No								
- Topographic map; Visual inspection (certification) of the proposed site									
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application	☐ Yes ☑ No ☐ NA								
(Applies to temporary, emergency, or cavitation pits and below-grade tanks)  - Visual inspection (certification) of the proposed site, Aerial photo; Satellite image	LI NA								
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application	☐ Yes ☐ No 図 NA								
<ul> <li>(Applies to permanent pits)</li> <li>Visual inspection (certification) of the proposed site, Aerial photo, Satellite image</li> </ul>	M NA								
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock	☐ Yes ⊠ No								
watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application  - NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site									
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes ⊠ No								
adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approval obtained from the municipality									
<ul> <li>Within 500 feet of a wetland</li> <li>US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site</li> </ul>	☐ Yes ☒ No								
Within the area overlying a subsurface mine  ☐ Yes ☑									
- Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division  Within an instable area									
<ul> <li>Within an unstable area</li> <li>Engineering measures incorporated into the design, NM Bureau of Geology &amp; Mineral Resources, USGS, NM Geological Society, Topographic map</li> </ul>	☐ Yes ⊠ No								
Within a 100-year floodplain - FEMA map									

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19 15 17 9 NMAC  Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15 17 9 NMAC  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC  Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC  Operating and Maintenance Plan - based upon the appropriate requirements of 19.15 17 12 NMAC  Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC  Previously Approved Design (attach copy of design) API Number or Permit Number
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15 17 9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Previously Approved Design (attach copy of design)  API Number
Previously Approved Operating and Maintenance Plan API Number (Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19 15 17 9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.    Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19 15 17 9 NMAC   Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC   Climatological Factors Assessment   Certified Engineering Design Plans - based upon the appropriate requirements of 19 15 17 11 NMAC   Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19 15 17 11 NMAC   Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19 15 17 11 NMAC   Quality Control/Quality Assurance Construction and Installation Plan   Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC   Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19 15 17 11 NMAC   Nuisance or Hazardous Odors, including H <sub>2</sub> S, Prevention Plan   Emergency Response Plan   Different Plan     Closure Plan - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Proposed Closure: 19 15 17 13 NMAC
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.  Type
Waste Excavation and Removal Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached.  Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17 13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)  Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC

d Steel Tanks or Haul-off Bins Only: (19 15 17 13 Is, drilling fluids and drill cuttings. Use attachment if I	O NMAC) more than two						
Disposal Facility Name Disposal Facility Permit Number							
Disposal Facility Name Disposal Facility Permit Number							
occur on or in areas that will not be used for future service.	vice and operations?						
ate requirements of Subsection H of 19 15 17 13 NMAO on Lof 19 15 17 13 NMAC	C						
ne closure plan. Recommendations of acceptable soun tire administrative approval from the appropriate disti- tal Bureau office for consideration of approval. Justi	rict office or may be						
ata obtained from nearby wells	☐ Yes ⊠ No ☐ NA						
ata obtained from nearby wells	☐ Yes ☒ No ☐ NA						
ata obtained from nearby wells	<ul><li>✓ Yes ☐ No</li><li>☐ NA</li></ul>						
ignificant watercourse or lakebed, sinkhole, or playa	☐ Yes ⊠ No						
	☐ Yes ☑ No						
r spring, in existence at the time of initial application	☐ Yes ⊠ No						
·	☐ Yes ☒ No						
sual inspection (certification) of the proposed site	☐ Yes 🖾 No						
ng and Mineral Division	☐ Yes ⊠ No						
ogy & Mineral Resources, USGS, NM Geological	☐ Yes ☑ No						
	☐ Yes ⊠ No						
	DI						
equirements of 19 15 17 10 NMAC of Subsection F of 19 15 17 13 NMAC appropriate requirements of 19 15 17 11 NMAC gpad) - based upon the appropriate requirements of 19 15 17 13 NMAC equirements of Subsection F of 19 15 17.13 NMAC of Subsection F of 19 15.17 13 NMAC d drill cuttings or in case on-site closure standards cann n H of 19 15 17 13 NMAC on I of 19 15 17.13 NMAC	15 17 11 NMAC						

Operator Application Certification:  I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief
Name (Print) Ben Mitchell Title Regulatory Specialist
Signature Date6/29/2011
e-mail address ben mitchell@williams.com Telephone 505-634-4206
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)  OCD Representative Signature: Approval Date: 3/01/2012  Title: OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 19 15 17 13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.  Closure Completion Date: 10/10/201
Closure Method:  Waste Excavation and Removal  On-Site Closure Method  Alternative Closure Method  Waste Removal (Closed-loop systems only)  If different from approved plan, please explain
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.  Disposal Facility Name Disposal Facility Permit Number  Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations?  Yes (If yes, please demonstrate compliance to the items below) No  Required for impacted areas which will not be used for future service and operations  Site Reclamation (Photo Documentation)  Soil Backfilling and Cover Installation  Re-vegetation Application Rates and Seeding Technique
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached.  □ Proof of Closure Notice (surface owner and division) □ Proof of Deed Notice (required for on-site closure) □ Plot Plan (for on-site closures and temporary pits) □ Confirmation Sampling Analytical Results (if applicable) □ Waste Material Sampling Analytical Results (required for on-site closure) □ Disposal Facility Name and Permit Numbei □ Soil Backfilling and Cover Installation □ Re-vegetation Application Rates and Seeding Technique □ Site Reclamation (Photo Documentation) □ On-site Closure Location Latitude _36 93288 Longitude _107 47696 NAD □1927 □1983
Operator Closure Certification:  I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief
Name (Print) Ben Mitchell  Signature Date: 2/38/30/3
e-mail address ben mitchell@williams com Telephone 505-333-1806



# WPX Energy Production, LLC San Juan Basin: New Mexico Assets

Temporary Pit In-place Closure Report Drilling/Completion and Workover (Groundwater >100 feet bgs)

Well: Rosa Unit #339A
API No: 30-045-31762

Location: 1-S32-T32N-R06W, NMPM

In accordance with Rule 19.15.17 13 NMAC, the following plan describes the general in-place closure requirements of temporary pits on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard procedure for all temporary pits to be utilized for the drilling, completion and/or workovers of oil and gas wells operated by WPX. For those temporary pits which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the pit closure on a Closure Report using Division Form C-144 The Report will include the following:

- Details on Capping and Covering, where applicable
- Plot Plan (Pit Diagram)
- Inspection reports
- Sampling Results
- Division Form C-105: WELL COMPLETION OR RECOMPLETION REPORT AND LOG
- Copy of Deed Notice filed with the County Clerk (format to meet County requirements)
   <u>A deed notice is not required on state, federal or tribal land according to NMOCD FAQ dated October 30, 2008 and posted on the NMOCD website</u>

#### General Plan Requirements:

1. All free standing liquids will be removed from the pit at the start of the closure process. Liquids will be removed in a manner that the appropriate District Office approves including; recycled, reused, reclaimed, evaporated, and/or disposed of in a Division-approved facility. Once all free liquids are removed, the sludge will be stabilized by one of the following methods depending on equipment availability. blending with clean stockpiled soils or dewatering using a Bowl Decanter Centrifuge then blending with clean stockpiles soils.

To the extent practical, free liquids were pulled from the reserve pit following the completion rigoff Haul dates were 10/11/2011 to the Rosa SWD #2 API # 30-039-30812 (Order -1236)

2 The preferred method of closure for all temporary pits will be on-site closure by in-place burial, provided all the criteria in 19 15.17 13 B are met.

On-site burial plan for this location was approved by the Aztec District Office on (7/6/2011

- 3 The surface owner shall be notified of WPX's proposed closure plan using a means that provides proof of notice (i.e. certified mail/return receipt requested)

  Williams notified the SMA of its intent to use a temporary pit and onsite burial in the Surface Use

  Plan in the well APD. The SMA was notified by email see attached. No return receipt required per BLM FFO/NMOCD MOU dated 5/4/09.
- 4 Within six months of the "rig-off" status occurring WPX will ensure that the temporary pit is covered, recontoured and reseeding in progress

  Drill rig-off 7/28/2011Completion rig-off 9/20/2011. Pit covered 10/10/2011Pit area along with unused portions of well pad to be interim reclaimed in accordance with Surface Management Agency requirements in APD-COAs and per BLM.FFO/NMOCD MOU dated 5/4/09.
- 5. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following
  - a Operators Name (WPX)
  - b. Well Name and API Number
  - c Location (USTR)

<u>The Aztec District Office of NMOCD was notified by email using a format acceptable to the District Copies of the notification from Abode Contractors on 9/27/2011)</u> is attached.

The pit liner shall be removed above "mud level" after stabilization. Removal of the liner will consist of manually or mechanically cutting the liner at the mud level and removing all remaining liner. Care will be taken to remove "all" of the liner (I.e. anchored material). All excessive liner will be disposed of at a licensed disposal facility (probably San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426)

The liner to the temporary pit was removed above the "mud level" once stabilized Removal of the liner consisted of manually cutting the liner and removing all remaining liner material above the "mud level" including the anchor material All excessive liner was disposed of at the San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

7. Solidification of the remaining pit contents shall be achieved by mixing non-waste containing, earthen material. The solidification process will be accomplished use a combination of natural drying and mechanical mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed safe and stable. The mixing ratio shall not exceed 3 parts non-waste to 1 part pit contents.

Following removal of free liquids, the pit contents were mixed with non-waste containing, earthen material in order to achieve appropriate solidification and a consistency that was deemed safe and stable. The solidification process was accomplished using a combination of natural drying, and mechanically mixing using a dozer and trackhoe. The mixing ration was approximately 2.5-3 parts native soil to 1 part pit contents. Solidification was completed 10/08/2011

8 A five-point composite sample will be taken of the pit using sampling tools and all samples tested per 19.15.17.13(B)(1)(b) NMAC In the event that the criteria are not met (See Table 1), all contents will be handled per 19.15.17.13(B)(1)(a) (i.e. dig and haul to a Division-approved facility) Approval to haul will be requested of the Aztec District office prior to initiation A five-point composite sampling was taken of the pit area using sampling tools and the sample was tested per 19.15.17.13(B)(1)(b) NMAC Results are shown in Table 1 and lab reports are attached

Table 1. Closure Criteria for Temporary Pits in Non-sensitive Areas with Groundwater >100 bgs.

Components	Testing Methods	<pre>\$Limits (mg/Kg)</pre>	Pit (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0 2	ND
BTEX	EPA SW-846 Method 8021B or 8260B	50	ND
TPH	EPA SW-846 Method 418 1	2500	Z
GRO/DRO	EPA SW-846 Method 8015M (GRO/DRO)	500	ND
Chlorides	EPA SW-846 Method 300 1	500	60

9 Upon completion of solidification and testing, the pit area will be backfilled with non-waste earthen material compacted to native conditions to enable effective revegetation for successful evapotranspiration. A minimum of four feet of cover including replacement of one foot of suitable material to establish vegetation, or the background thickness of topsoil, whichever is greater.

<u>Upon completion of solidification and testing, the pit area was backfilled with non-waste earthen</u> material compacted to native conditions. A minimum of four feet of cover to the extent practical was achieved and the cover included just over a foot of topsoil suitable to establish vegetation.

10 Following cover, the site will be recontoured to meet the Surface Management Agency or surface owner requirements Re-contouring will attempt to match fit, shape, line form, and texture of the surrounding geography Re-shaping will include drainage control, prevent ponding, and minimize erosion Natural drainages will be unimpeded and stormwater Best Management Practices (BMPs) will be used to aid in soil stabilization and protection surface water quality.

Following cover, Williams reestablished drainage and contours to approximately match previous topography meeting the Conditions of Approval in the APD and the direction offered by a BLM/USFS inspector. Cover and re-contouring were completed 10/10/2011

- Notification will be sent to the Aztec District office when the reclaimed area is seeded Williams will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM.FFO/NMOCD MOU dated 5/4/09.
- 12 WPX shall seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth.

Page 8 of 9 Rosa Unit 339A

occurs Note WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) or Land owner as part of a surface use agreement or APD are Division-approved methods unless notified by the Division of their unacceptability.

Williams will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM\*FFO/NMOCD MOU dated 5/4/09.

13 The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the on site burial upon the abandonment of all wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the on site burial of the temporary pit. The plate will be easily removable and a four-foot tall riser will be threaded into the top of the collar marker and welded around the base with the operations information at the time of all wells on the pad abandoned. The information will include Operator Name, Lease Name, Well Name, and number, USTR, and an indicator that the marker is an onsite pit burial location.

The temporary pit was located with a steel marker meeting the above listed specifications. The marker has the following information welded for future reference: Williams Production, NMSF-078768, S32-T32N-R06W-I, "In Place Burial" (photo attached). Steel marker set 12/14/2011

Page 9 of 9 Rosa Unit 339A

# CHAIN OF CUSTODY RECORD

12899

Client:			Project Name /						ANALYSIS / PARAMETERS													
WPX			20517 Un	1+# 3	39 A					,		,			· ·				 <del>,</del>	,		,
Client Address:			Sampler Name:						2	[2]	9		e e									
			BRIANF	ERRY	,				8	8	826	2	_		_					]		
Client Phone No.:			Client No.:							ļ ģ	pod	leta	nioin		至		F.	ய			100	tact
			C	410	8-01	No /Volume			TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P		TPH (418.1)	CHLORIDE			Sample Cool	Sample Intact
Sample No./	Sample	Sampl	e Lab No.	S	ample	No /Volume of	Pres	ervati	폐물	Ĭ Ä	ő	Ä	tion	5	듯	PAH	<u>F</u>	일			dun	m d
Identification	Date	Time	Eds No.		//atrix	Ontainers	HgCl,	HCI	<u> </u>	18	>	<u> </u>	ర	RCI	<u> </u>	8	片	<u>5</u>	 		Š	လိ
ROTA UNITE 339.A	11-4-11	11:30 A	m 60220	Soil Solid	Sludge Aqueous	.1_			V	V								i/			ست	/
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous					<u> </u>											_	_
1				Soil Solid	Sludge Aqueous											-						
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous										-							
	ture)			·	Date	Time	R	ecen	ed by:	(Sign	ature)								 Da	ate	Til	ne
3	=				11-7-11	8:45 A	. [					-	,	~					11/7	11	SIL	154
Relinquished by: (Signa	ture)							eceiv	ed by:	(Sign	ature)							_ 16.00	 	<del>_</del> , •		
Relinquished by: (Sıgna	ture)	<u></u>	<del></del>			<u> </u>	Re	eceiv	ed by:	(Sign	ature)		·							<u> </u>		
Relinquished by: (Signal Relinquished by: (Sig	ture)	ie Le	ure		11-7-11	Time 8:45 14	Re	eceiv	ved by:	(Sign	ature)		,	~			•		Da		1	



5796 US Highway 64 • Farmington, NM 87401 • 505-632-0615 • lab@envirotech-inc.com



## EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client: WPX Project #: 04108-0136 Sample ID: 11-09-11 Rosa Unit #339 A Date Reported: 60220 11-04-11 Laboratory Number: Date Sampled: 12899 11-07-11 Chain of Custody No: Date Received: Sample Matrix: Soil Date Extracted: 11-08-11 Preservative: Cool 11-08-11 Date Analyzed: Condition: Intact 8015 TPH Analysis Requested:

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum	ND	

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid

Waste, SW-846, USEPA, December 1996.

Comments:

Rosa Unit #339 A

5796 US Highway 64 Farmington NM 8740

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



# EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

## **Quality Assurance Report**

Client:	QA/QC	Project #:	N/A
Sample ID:	11-08-11 QA/QC	Date Reported:	11-09-11
Laboratory Number:	60214	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	11-08-11
Condition:	N/A	Analysis Requested:	TPH

	I Cal Date	JEÇâl RÊ:	c:cal RF	Difference	Accept. Range
Gasoline Range C5 - C10	11-08-11	9.996E+02	1.000E+03	0.04%	0 - 15%
Diesel Range C10 - C28	11-08-11	9.996E+02	1.000E+03	0.04%	0 - 15%

Blank(Conc:((mg/៤≒ mg/Kg)).⊸ ∈	"Concentration	Detection Limit
Gasoline Range C5 - C10	7.7	0.2
Diesel Range C10 - C28	3.4	0.1

Duplicate Conc. (mg/Kg)	Sample	Duplicate 🖖	% Difference.	Range
Gasoline Range C5 - C10	ND	ND	0.00%	0 - 30%
Diesel Range C10 - C28	94.4	94.9	0.46%	0 - 30%

Spike Conc. (mg/Kg)	: Sample	Spike Added	Spike Result	%Recovery	Accept! Range 7.
Gasoline Range C5 - C10	ND	250	236	94.4%	75 - 125%
Diesel Range C10 - C28	94.4	250	338	98.2%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid

Waste

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 60214-60216, 60219-60221.

Review



#### **EPA METHOD 8021 AROMATIC VOLATILE ORGANICS**

Client:	WPX	Project #:	04108-0136
Sample ID:	Rosa Unit # 339A	Date Reported	11-09-11
Laboratory Number:	60220	Date Sampled:	11-04-11
Chain of Custody:	12899	Date Received:	11-07-11
Sample Matrix:	Soil	Date Analyzed:	11-08-11
Preservative:	Cool	Date Extracted:	11-08-11
Condition:	Intact	Analysis Requested:	BTEX
		Dilution:	10

Concentration (ug/Kg)	Det. Limit (ug/Kg)	
ND	0.9	
ND	1.0	
ND	1.0	
ND	1.2	
ND	0.9	
	(ug/Kg)  ND ND ND ND ND ND	Concentration (ug/Kg)         Limit (ug/Kg)           ND         0.9           ND         1.0           ND         1.0           ND         1.0           ND         1.2

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	82.0 %
	1,4-difluorobenzene	95.0 %
	Bromochlorobenzene	98.7 %

References:

**Total BTEX** 

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

ND

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Rosa Unit #339 A



#### **EPA METHOD 8021** AROMATIC VOLATILE ORGANICS

Client:	N/A	F	Project #:		N/A		
Sample ID:	1108BCAL QA/Q0	2	Date Reported:		11-09-11		
Laboratory Number:	60214		Date Sampled:		N/A		
Sample Matrix:	Soil	ſ	Date Received:		N/A		
Preservative:	N/A	Ţ	Date Analyzed:		11-08-11		
Condition:	N/A	,	Analysis:		BTEX		
		ı	Dilution:		10		
Calibration (and	Ecal RF	C-Cal RF.	%Diff:	Blank	Detect:	1 45 T	
Detection(Limits (ug/L))		C Cal RE	e 0 - 15%	Conc	Limit	2 45	
Detection Limits (ug/L) Benzene	7.0648E+003	C-Cal RF. Accept: Rang 7.0790E+003	e 0 ⇒ 15% 0.2%	Čonc: ND	Climit, 0.1	45.7	
Detection Limits (ug/L) Benzene Toluene		C Cal RE	e 0 ≥ 15% 0.2% 0.2%	Conc ND ND	0.1 0.1	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
Detection Limits (ug/L) Benzene	7.0648E+003	C-Cal RF. Accept: Rang 7.0790E+003	e 0 ⇒ 15% 0.2%	Čonc: ND	Climit, 0.1	1 49 m	
Detection Limits (ug/L) Benzene Toluene	7.0648E+003 1 1848E+004	C Cal RF Accept: Rang 7.0790E+003 1.1872E+004	e 0 ≥ 15% 0.2% 0.2%	Conc ND ND	0.1 0.1	2 45	

Duplicate Conc (ug/Kg)	Sample Di	iplicate 💢 😲	%Diff.	Accept Range.	/Detect/Limit
Benzene	ND	ND	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9

Spike Conc. (ug/Kg)	, Sample Amo	unt Spiked Spik	ed Sample :: %	Recovery	Accept Range	1
Benzene	ND	500	436	87.3%	39 - 150	
Toluene	ND	500	438	87.6%	46 - 148	
Ethylbenzene	ND	500	433	86.7%	32 - 160	
p,m-Xylene	ND	1000	867	86.7%	46 - 148	
o-Xylene	ND	500	433	86.7%	46 - 148	

ND - Parameter not detected at the stated detection limit.

Dilution: Spike and spiked sample concentration represent a dilution proportional to sample dilution.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using

Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 60214-60216, 60219-60221

Review



### **Chloride**

**WPX** Client: Project #: 04108-0136 Sample ID: Rosa Unit #339 A Date Reported: 11-09-11 Lab ID#: 60220 11-04-11 Date Sampled: Date Received: 11-07-11 Sample Matrix: Soil Preservative: Cool Date Analyzed: 11-08-11 Condition: Chain of Custody: Intact 12899

**Parameter** Concentration (mg/Kg)

**Total Chloride** 

60

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Rosa Unit #339 A

5796 US Highway 64, Farmington, NM 87401

Review

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com

District I 1625 N. French Dr., Hobbs, NM 88240

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised October 12, 2005 Instructions on back Submit to Appropriate District Office

District II 1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

District III

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505 State Lease - 4 Copies Fee Lease - 3 Copies

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

AMENDED REPORT


#### WELL LOCATION AND ACREAGE DEDICATION PLAT

'API Number	*Pool Code	Pool Name				
30-045-31762	71629	1629 BASIN FRUITLAND COAL				
'Property Code	*Property	*Well Number				
17033	ROSA (	339A				
'0GRID No.	*Operator	*Elevation				
120782	WILLIAMS PRODUC	6373				

<sup>10</sup> Surface Location

UL or lot no	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
I	32	32N	6W		1353	SOUTH	1045	EAST	SAN JUAN
		11 E	ottom	Hole L	ocation I	f Different	From Surf	ace	
UL or lot no	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
G	32	32N	БW		2350	NORTH	1961	EAST	SAN JUAN
12 Dedicated Acres		0.0 Acre	s – (E	[/2)	<sup>13</sup> Joant or Infall	<sup>54</sup> Consolidation Code	<sup>25</sup> Order No		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



### Meador, Tasha

From: Sent: johnny@adobecontractorsinc com Monday, January 30, 2012 1:03 PM

To:

Meador, Tasha

Subject:

FW: Williams Clean up Rosa Unit #339 A

Here is the 339A There is only the one to Brandon because it is a state location.

Johnny Stinson

Gen. Manager/ Adobe Contractors

Office: (505)632-1486 Mobile<sup>-</sup> (505)320-6076

johnny@adobecontractorsinc.com

**From:** Glenn Shelby [mailto:glenn@adobecontractorsinc.com]

Sent: Tuesday, September 27, 2011 9:07 AM

To: Brandon Powell

Cc: Stanley Dean; Johnny Stinson; Levi Thorson; Mark Lepich; Chris Lucero; Ben Mitchell; Tasha Meador; Cyd Hemphill;

Lacey Granillo

Subject: Williams Clean up Rosa Unit #339 A

Brandon,

We will be ready to start the clean up on the Rosa Unit # 339A this week. Please let me know if you have any questions.

Thanks,

Glenn Shelby Field Foreman Adobe Contractors, Inc Cell: 505-320-7187

glenn@adobecontractorsinc.com

Iwo Copies	Two Copies						/lexico					· ·			rm C-105
District I 1625 N French Dr	· Hobbs NM 8	38240	Ene	ergy, I	Minerals and	d Na	itural R	esources		1 WELL	APÎ']	NO.	-		July 17, 2008
District II 1301 W Grand Av	enue, Artesы,	NM 88210		Oi	l Conservat	ion	Divisi	on		30-045-3170	<u>62</u>	- Andrews			
District III 1000 Rio Biazos R	d A∠tec NM	87410			20 South St					2 Fype of L		☐ FEE	F	ED/IND	IAN .
District IV 1220 S St Francis	Dι Santa Γe	NM 87505			Santa Fe, N	IM	87505			3 State Oil a		William District			
		TION OR	RECO	MPL	ETION RE	PO	RT AN	D LOG			C ALMONDO CONTRA	SHIPS DISABLED OF SPECIAL	ononistaniai n	Chi. Vitation and China St. St.	
4 Reason for fil										5 Lease Nam	ic oi U	(m) share a woman	ment Na osa	ime	
COMPLET	ION REPOI	gh #31	for State and Fee	e well	s only)			6 Well Number							
☑ C-144 CLOSURE ATTACHMENT (Fill in boxes #1 through #9, #15 Date Rig Released a #33, attach this and the plat to the C-144 closure report in accordance with 19 15 17 13 K NMAG								/oı	Total and the second	redect	Rosa Ur	nt #339.	A		
7 Type of Com	pletion		·		□PLUGBAC				/OIR	OTHER				•	
8 Name of Oper						<u>`                                    </u>	DITTERE			9 QGRID	1207	782		<u> </u>	
10 Address of O	perator P (	O BOX 640	AZTE	C, NM	87410					11 Pool name	or W	ıldeat			-
12 Location	Unit Lti	Section	Townsl	hip	Range	Lot		Feet from t	he	N/S Line	Feet	fiom the	E/W L		County
Surface:											1				
BH:															
13 Date Spudde	d   14 Date	T D Reached	15 <u>D</u>	ate Rig	Released 9/20/2011		16	Date Compl	leted	(Ready to Pro	duce)		'Elevat Γ, GR, e		and RKB,
18 Total Measur	red Depth of	Well	19 P	lug Bac	k Measured Dep	oth	20	Was Direct	liona	l Survey Made	9	21 Тур	e Electii	ic and Ot	her Logs Run
22 Producing In	terval(s), of t	his completion	- Top, Bott	tom, Na	nme				-			•			
23				CAS	ING REC	OR	D (Rep	ort all st	ring	gs set in w	ell)		-		<del> </del>
CASING SI	IZE	WEIGHT LE			DEPTH SET			OLE SIZE	`	CEMENTIN		CORD	A۱	MOUNT	PULLED
		<del></del>													
		<u> </u>				_									
24				LIN	ER RECORD				25		ΓUΒΙΙ	NG REC	ORD		
SIZE	TOP	В	OTTOM		SACKS CEM	ENT	SCREE	N	SIZ	ZE	DI	EPTH SET	-	PACK	ER SET
											丄				
26 Perforation	record (inter	ıval, sıze, and r	umber)					CID, SHOT, I INTERVAL		ACTURE, CE AMOUNT A					
•							DEIT	THYLERVAL		ZUMOGIVIZ	1100	CITY MITT	TERMITE	OSED	
										<del>                                      </del>					
28						PR	ODUC	TION							
Date First Produ	ction	Produ	ction Meth	od (Fla	owing, gas lift, pi				)	Well Status	s (Pro	d or Shut-	ın)		
					,										
Date of Test	Hours Te	ested	hoke Size		Prod'n For Test Perrod		Oil - Bl	ol <b> </b>	Gas	s - MCF	W	ater - Bbl		Gas - C	Dil Ratio
Flow Tubing	Casing P		alculated 2	:4-	Oıl - Bbl		Gas	s - MCF		Water - Bbl		Oil Gra	vity - Al	 PI <i>- (Coi</i>	1)
Press			lour Rate								130.5				
29 Disposition of	•	usea Joi Juei, ve	eniea eic)								30 1	Test Witne	ssea By		
31 List Attachm	ients														
32 If a temporar															
33 If an on-site	burial was us	ed at the well, i	eport the e	xact loc	The second of the second of the second			tude 107 476	506	NAD	1083				
I hereby certi												knowled	lge and	d beliej	· · · · · · · · · · · · · · · · · · ·
	en Mitchel	11 / A	Printed N	vame		7	Fitle P	amilatam (	Sno	cialist <u>Dat</u>	ຼ່ງ	Jash	1/7		
Signature							ine K	egulatory S	spe	vialist <u>Dati</u>	~_ <b>~</b>	100 ( de	LICE		
E-mail Addre	ess ben m	itchel <u>l(a)</u> wpx	cenergy c	<u>com</u>											



# **TEMPORARY PIT INSPECTION REPORT**

Well Name	Rosa Unit 339A	Field Name	Basın FC	API#	30-045-31762	Report #	1
Location	? FNL & 2525? FEL Sec 32, T32N,	County	San Juan	State	NM	Rpt Date	7/12/2011

Location	1112	25257 FEL Sec 3	Z, TOZIN,	County	<u></u>	San Juan		State	NM   Rpt Date   7/12/2011
Date	Report Type	Inspector	Liner Intact Y/N	Fenced Y/N	Slopes Intact Y/N	Adequate Freeboard Y/N	Oil Free Y/N	Flare Pit Liquid Free Y/N	Comment
7/12/11	Daily		Υ	Y	Υ	Y	Υ	Y	
7/13/11	Daily		Υ	Y	Υ	Y	Y	Υ	Phone (505)801-0826
7/14/11	Daily		Υ	Y	Υ	Y	Y	Y	Phone (505)801-0826
7/15/11	Daily		Υ	Y	Υ	Y		Y	Phone (505)801-0826
7/16/11	Daily		Υ	Y	Υ	Υ	Υ	Y	Phone (505)801 - 0826
7/17/11	Daily		Υ	Y	Υ	Y	Y	Y	Phone (505)801-0826
7/18/11	Daily		Υ	Υ	Υ	Υ	Y	Y	Phone (505)801-0826
7/19/11	Daily		Υ	Υ	Υ	Υ	Y	Y	Phone (505)801-0826
7/20/11	Daily		Υ	Υ	Υ	Y	Y	Y	Phone ( 505 ) 801-0826
7/21/11	Daily		Υ	Y	Υ	Υ	Y	Y	Phone (505)801-0826
7/22/11	Daily		Y	Y	Y	Y	Υ	Y	Phone (505)801-0826
7/23/11	Daily		Y	Y	Y	Y	Y	Y	Phone (505)801-0826
7/24/11	Daily		Υ	Y	Υ	Υ	Y	Υ	Phone (505)801-0826
7/25/11	Daily		Υ	Υ	Υ	Υ	Y	Y	Phone (505)801-0826
7/12/11	Daily		Y	Υ	Y	Y	Y	Y	NEW reserve pit
7/13/11	Daily		Y	Υ	Υ	Y		Υ	New resevre pit
7/19/11				Υ	Υ	Y	Y	Y	
7/28/11	Daily		Υ	Υ	Y	Y	Y	Y	
9/3/11	Daily		Υ	Υ	Y	Y	Y	Υ	
9/4/11	Daily		Υ	Y	Υ	Υ	Y	Y	
9/7/11	Daily		Y	Υ	Υ	Y	Y	Y	
9/8/11	Daily		Υ	Υ	Υ	Y	Y	Υ	
9/9/11	Daily		Y	Y	Υ	Y	Y	Y	
9/10/11	Daily		Y	Y	Y	Y	Y	Y	
9/11/11	Daily		Y	Y	Υ	Y	Y	Υ	
9/12/11	Daily		Y	Y	Υ	Y	Y	Y	
9/13/11	Daily		Y	Y	Υ	Y	Y	Υ	
9/14/11	Daily		Y	Υ	Υ	Y	Υ	Y	
9/15/11	Daily		Υ	Υ	Υ	Y	Y	Y	
9/16/11	Daily		Y	Y	Y	Y	Y	Y	
9/17/11	Daily		Y	Y	Y	Υ	Y	Y	
9/18/11	Daily		Y	Y	Υ	Y	Y	Y	
9/19/11	Daily		Υ	Υ	Υ	Y	Y	Y	
9/20/11	Daily		Υ	Υ	Υ	Y	Y	Y	
9/21/11	Daily		Υ	Υ	Υ	Y	Y	Υ	
8/3/11	Weekly		Υ	Y	Υ	Y	Y	Y	
8/14/11	Weekly		Y	Y	Υ	Y	Υ	Y	
8/17/11	Weekly		Υ	Y	Y	Y	Υ	Y	
8/25/11	Weekly		Υ	Y	Υ	Y	Υ	Y	
8/30/11	Weekly		Υ	Υ	Υ	Υ	Y	Y	
		·= ··· ·							
	_								
		-							
			20	01-2009 WellF	z Information M	lanagement, LLC All	nohts res	erved ver 111700ic	



