

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-09319

OPERATOR

☐ Initial Report

☒ Final Report

| | | | |
|-----------------|--|---------------|-------------------------|
| Name of Company | Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company | Contact | Kelsi Harrington |
| Address | 3401 E. 30th St., Farmington, NM 87402 | Telephone No. | 505-599-3403 |
| Facility Name | Aztec Federal 1 | Facility Type | Gas Well |
| | | API# | 3004509319 |
| Surface Owner | Federal | Mineral Owner | Federal |
| | | Lease No. | SF-078171 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|-----------|------------|------------|---------------|------------------|---------------|----------------|-----------------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| J | 24 | 30N | 11W | 1560' | South | 1850' | East | San Juan |

Latitude **36.78703° N** Longitude **-107.94765° W**

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release – Unknown | Volume of Release – unknown | Volume Recovered – |
| Source of Release: Below Grade Tank | Date and Hour of Occurrence unknown | Date and Hour of Discovery 11/2/09 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour – | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Below grade tank closure activities. | | |
| Describe Area Affected and Cleanup Action Taken.* No sample was available from the bottom due to encountering bedrock, therefore a composite of the walls was taken. The sample returned the following results: USEPA Method 8015- Non Detect, USEPA Method 8021- Non Detect & Chlorides- 95 ppm; therefore no further action is required. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <i>Kelsi Harrington</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Kelsi Harrington | Approved by District Supervisor: <i>Janet D. Kelly</i> | |
| Title: Environmental Consultant | Approval Date: <i>2/29/2012</i> Expiration Date: | |
| E-mail Address: kelsi.g.harrington@conocophillips.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 9/27/10 Phone: 505-599-3403 | | |

* Attach Additional Sheets If Necessary

nJK1206054675

