

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-045-09376

**OPERATOR**

Initial Report  Final Report

Name of Company BP	Contact: Courtney Cochran
Address: 200 Energy Court, Farmington, NM 87401	Telephone No : 326-9457
Facility Name. Florence O 020-MV	Facility Type: natural gas well API #: 300450937600

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 078201
------------------------	------------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	T30N	R9W	990	North	650	East	San Juan

Latitude\_36.8012 Longitude\_107.72802

**NATURE OF RELEASE**

Type of Release produced water	Volume of Release approx. 20 bbl of produced water	Volume Recovered none
Source of Release BGT	Date and Hour of Occurrence 10/21/10	Date and Hour of Discovery 10:00 AM on the 10/22/10
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD NOV 1 '10

If a Watercourse was Impacted, Describe Fully \*

**OIL CONS. DIV.  
DIST. 3**


Describe Cause of Problem and Remedial Action Taken \*

Stormwater runoff from a heavy rain filled the BGT and subsequently ran it over. The tank had approximately 20 bbl of produced water in it before the event The pit was pulled after the event, and all contents removed

Describe Area Affected and Cleanup Action Taken \*

The berm will be repaired.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name Courtney Cochran	Approved by District Supervisor 	
Title Environmental Challenger	Approval Date 3/06/2012	Expiration Date
E-mail Address Courtney Cochran@bp.com	Conditions of Approval	Attached <input type="checkbox"/>
Date October 29, 2010	Phone 326-9457	

\* Attach Additional Sheets If Necessary

NJK 1206649886