

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-28051

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Jeff Peace
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9479
Facility Name: Florance No. Z-3	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 078578
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter G	Section 21	Township T30N	Range R8W	Feet from the 1530	North/South Line North	Feet from the 1790	East/West Line East	County: San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------------

Latitude 36.79992 Longitude 107.67810

NATURE OF RELEASE

Type of Release: Natural gas	Volume of Release: approx. 108 mcf	Volume Recovered: none
Source of Release: ball valve	Date and Hour of Occurrence: approx. 2:00 PM, 6/22/10	Date and Hour of Discovery: 11:00 AM, 6/25/10
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RCVD JUL 2 '10
OIL CONS. DIV.
DIST. 2

Describe Cause of Problem and Remedial Action Taken.*

A compressor mechanic left a 1" ball valve on the suction scrubber line open after servicing the compressor. After the compressor was placed back in service gas leaked through the open valve until it was found by the well operator. The valve was closed and the compressor company was notified of the incident.

Describe Area Affected and Cleanup Action Taken.*

The released gas dissipated into the atmosphere. No cleanup was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeffrey H. Peace</i>		OIL CONSERVATION DIVISION	
Printed Name: Jeffrey H. Peace		Approved by District Supervisor: <i>Jonathan D. Kelly</i>	
Title: HSE Advisor		Approval Date: 2/29/2012 Expiration Date:	
E-mail Address: peace.jeffrey@bp.com		Conditions of Approval:	
Date: June 30, 2010 Phone: 326-9479		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

JK 1206037091