

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-345-30582

<b>OPERATOR</b>		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	ConocoPhillips Company	Contact	Kelsi Harrington
Address	3401 E. 30 <sup>th</sup> St., Farmington, NM 87402	Telephone No.	505-599-3403
Facility Name	Moore LS 7B	Facility Type	Gas Well API #3004530582
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078147

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	32N	12W	745'	North	1960'	East	San Juan

Latitude 36.9617° N Longitude -108.04401° W

RCVD NOV 17 10  
OIL CONS. DIV.  
DIST. 3

**NATURE OF RELEASE**

Type of Release – <b>Produced Water</b>	Volume of Release – <b>18 BBL</b>	Volume Recovered – <b>0 BBL</b>
Source of Release: <b>Production Tank</b>	Date and Hour of Occurrence <b>unknown</b>	Date and Hour of Discovery <b>10/20/10 1:15 p.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour –	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\* **On October 20, 2010, it was discovered that the bottom of the Production tank had developed a leak. Upon discovery, the well was shut in and the fluids in the tank were transferred to a temporary tank.**

Describe Area Affected and Cleanup Action Taken.\* **All fluids remained within the berm & no fluids were recovered. Confirmation sampling occurred and analytical results were below the regulatory standards set forth in the NMOCD Guidelines for Remediation of Leaks, Spills and Releases; therefore no further action is needed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Harrington</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kelsi Harrington</b>	Approved by District Supervisor: <i>Jonathan D. Kelly</i>	
Title: <b>Environmental Consultant</b>	Approval Date: <i>3/6/2012</i>	Expiration Date:
E-mail Address: <b>kelsi.g.harrington@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>11/2/10</b> Phone: <b>505-599-3403</b>		

\* Attach Additional Sheets If Necessary

WJK 1206651737