15

District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources** Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to

the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Alternative Method:

Pit, Closed-Loop System, Below-Grade Tank, or

9902 Pro	oposed Alternative Method	Permit or Closure Pl	an Application	
Type of acti	on: Permit of a pit, closed-loop Closure of a pit, closed-loop Modification to an existing Closure plan only submitted	system, below-grade tank, o permit I for an existing permitted or i	r proposed alternative meth	hod
_	• •			
lease be advised that approval of t	this request does not relieve the operator of lelieve the operator of its responsibility to cor	iability should operations result in	pollution of surface water, grou	und water or the
	Farmington, New Mexico 87401			
	ght State COM 1E			
API Number: 3004525930	OCD Pe	ermit Number:		
U/L or Qtr/QtrI Sect	tion 36 Township 32N	_ Range13W County:	San Juan	<u>.</u>
Center of Proposed Design: Lat	titude <u>36.93996</u> Longitu	ide <u>-108.14799</u>	NAD: □1927 🛭 1983	
Surface Owner Federal S	State 🗌 Private 🔲 Tribal Trust or Indian	Allotment		
2				
☐ <u>Pit</u> : Subsection F or G of	19.15.17.11 NMAC		RCVD APR	
Temporary: Drilling Wo	orkover		OIL COMS	
☐ Permanent ☐ Emergency ☐	☐ Cavitation ☐ P&A		Ciot.	. <u> </u>
☐ Lined ☐ Unlined Liner t	ype Thicknessmil 🔲 LLD	PE HDPE PVC Oth	er	
String-Reinforced				
Liner Seams: Welded Fa	actory Other	Volume:bbl	Dimensions: L x W	x D
3.	section H of 19.15.17 11 NMAC			
intent)	Drilling a new well Workover or Dr		h require prior approval of a p	permit or notice of
	und Steel Tanks 🔲 Haul-off Bins 🔲 C			
	be Thickness mil L		Other	
Liner Seams: Welded Fa	actory Other			
4 X Below-grade tank: Subsect	ion I of 19.15.17 11 NMAC			
Volume:	bbl Type of fluid Produ	uced Water	:	
Tank Construction material:				
Secondary containment with	n leak detection 🔲 Visible sidewalls, lir	ner, 6-inch lift and automatic ove	rflow shut-off	
☐ Visible sidewalls and liner	X Visible sidewalls only Other		•	
	mil			
5.				

Submittal of an exception request is required Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify	hospital,
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other	
Monthly inspections (If netting or screening is not physically feasible)	
8. Signs: Subsection C of 19.15.17.11 NMAC ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers ☐ Signed in compliance with 19.15.3.103 NMAC	
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying above-grade tanks associated with a closed-loop system.	priate district pproval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☑ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) - Topographic map; Visual inspection (certification) of the proposed site	Yes □ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☑ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☑ NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application NM Office of the State Engineer - IWATERS database search, Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☒ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☒ No
Within an unstable area. - Engineering measures incorporated into the design; NM Burcau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☑ No
Within a 100-year floodplain. , - FEMA map	☐ Yes ☑ No

11. Temporary Pits Emergency Pits and Relow-grade Tanks Permit Application Attachment Checklist: Subsection B of 10.15.17.0 NMAC					
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are					
attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17 10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC					
Previously Approved Design (attach copy of design) API Number: or Permit Number:					
Treviously Approved Design (attach copy of design) Art Number.					
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC					
Previously Approved Design (attach copy of design) API Number					
Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use					
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)					
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Gil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC					
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)					
Waste Excavation and Removal Closure Plan Checklist: (19.15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17 13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC					

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins On Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings.	
facilities are required.	
Disposal Facility Name: Disposal Facility Permit Number:	
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used. Yes (If yes, please provide the information below) No	used for future service and operations?
Required for impacted areas which will not be used for future service and operations Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	19.15.17 13 NMAC
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of provided below. Requests regarding changes to certain siting criteria may require administrative approval from the considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	e appropriate district office or may be
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, si lake (measured from the ordinary high-water mark). - Topographic map, Visual inspection (certification) of the proposed site	nkhole, or playa Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial a - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	pplication. Yes No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for dom watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of in NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal dopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	sipal ordinance Yes No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the p	proposed site
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS, NN Society; Topographic map 	M Geological Yes No
Within a 100-year floodplain - FEMA map	Yes No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17. Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate re Protocols and Procedures - based upon the appropriate requirements of 19.15.17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15. Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15 17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC	AC 7.11 NMAC equirements of 19.15.17.11 NMAC 5.17.13 NMAC

)	
Operator Application Certification:	
I hereby certify that the information submitted with this application is true, accur	ate and complete to the best of my knowledge and belief.
Name (Print): Tit	:le:
Signature:	Date:
e-mail address:Telephone:	
OCD Approval: Permit Application (including closure plan) Closure Poch Representative Signature: Title:	OCD Conditions (see attachment) Approval Date: 4/9/2012 OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection Instructions: Operators are required to obtain an approved closure plan prior to The closure report is required to be submitted to the division within 60 days of to section of the form until an approved closure plan has been obtained and the closure plan plan has been obtained and the closure plan plan plan plan plan plan plan plan	to implementing any closure activities and submitting the closure report. he completion of the closure activities. Please do not complete this
22. Closure Method: ☐ Waste Excavation and Removal ☐ On-Site Closure Method ☐ Alterna ☐ If different from approved plan, please explain.	ative Closure Method Waste Removal (Closed-loop systems only)
Closure Report Regarding Waste Removal Closure For Closed-loop Systems Instructions: Please indentify the facility or facilities for where the liquids, drift two facilities were utilized. Disposal Facility Name: Were the closed-loop system operations and associated activities performed on or Yes (If yes, please demonstrate compliance to the items below) No Required for impacted areas which will not be used for future service and operate Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	Disposal Facility Permit Number: Disposal Facility Permit Number: in areas that will not be used for future service and operations?
24. Closure Report Attachment Checklist: Instructions: Each of the following it mark in the box, that the documents are attached. □ Proof of Closure Notice (surface owner and division) □ Proof of Deed Notice (required for on-site closure) □ Plot Plan (for on-site closures and temporary pits) □ Confirmation Sampling Analytical Results (if applicable) □ Waste Material Sampling Analytical Results (required for on-site closure) □ Disposal Facility Name and Permit Number □ Soil Backfilling and Cover Installation □ Re-vegetation Application Rates and Seeding Technique □ Site Reclamation (Photo Documentation) ○ On-site Closure Location: Latitude Longing	ems must be attached to the closure report. Please indicate, by a check
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure belief I also certify that the closure complies with all applicable closure requirements.	
Name (Print): Ed Hasely	Title Sr Environmental Engineer
Signature. Hasely	Date: 4/11/12
e-mail address: ed.hasely@energen.com	Telephone: (505) 324-4131

BELOW-GRADE TANK CLOSURE REPORT

ENERGEN RESOURCES Wright State Com #1E

CLOSURE STEPS: (Closure Report information is in **bold**)

- (1) Notify the surface owner by certified mail, return receipt requested, of the plans to close the below-grade tank.

 Attached
- (2) Notify the Aztec OCD office (Brandon Powell 334-6178, Ext 15) verbally or by other means at least 72 hours, but not more than one week, prior to the planned closure operation.

Attached

- (3) Remove liquids from the below-grade tank. Dispose of the liquids and sludge in a division-approved facility.

 No disposal of liquids was required.
- (4) Remove the below-grade tank for re-use in an above-ground setup or for disposal in a division-approved manner.

 Tank removed.
- (5) Unless the equipment is required for some other purpose, remove any on-site equipment associated with the below-grade tank.

All remaining equipment is required for operations.

- (6) Test the soils beneath the below-grade tank to determine whether a release has occurred.
 - Collect, at a minimum, a five point, composite sample;
 - Composite sample was collected.
 - Collect individual grab samples from any area that is wet, discolored or showing other evidence of a release;

No additional sampling was necessary.

Analyze for BTEX, TPH and chlorides to demonstrate:

- Benzene concentration does not exceed 0.2 mg/kg, as determined by EPA SW-846 methods 8021B or 8260B
- Total BTEX concentration does not exceed 50 mg/kg, as determined by EPA SW-846 methods 8021B or 8260B
- TPH concentration does not exceed 100 mg/kg, as determined by EPA method 418.1
- Chloride concentration does not exceed 250 mg/kg, as determined by EPA method 300.1 or the background concentration, whichever is greater.

Constituent	Limit (mg/kg)	Actual Results (mg/kg)
Benzene	0.2	ND
Total BTEX	50.0	ND
TPH (418.1)	100	25.7
Chlorides	250	95

(7) <u>IF the soil analyses show that the soils meet the concentrations specified in (6) above,</u> backfill the excavation with compacted, non-waste containing, earthen material in a manner that will prevent ponding or erosion. If the area will not be needed for operations, reclaim the area as described in the "RECLAMATION" section.

Excavation was backfilled w/ non-waste containing, earthen material in a manner that will prevent ponding and erosion, including one foot of top soil.

(8) <u>IF the soil analyses show that the soils exceed one or more of the concentrations specified in (6) above, notify the Aztec OCD office (Brandon Powell – 334-6178, Ext 15) and proceed per 19.15.3.116 NMAC.</u>

Not applicable.

NOTE: If groundwater is encountered at any time during the closure process, the OCD office will be notified and a specific closure plan will be submitted to the Aztec and Santa Fe OCD offices for approval.

Not applicable.

FINAL CLOSURE REPORT:

Within 60 days of closure completion, submit a closure report on form C-144, with necessary attachments to document all closure activities including sampling results.

This submittal is the closure report.

RECLAMATION:

If the area is not needed for operations, reclaim the area to a safe and stable condition that blends with the surrounding undisturbed area. Restore the impacted surface area to the condition that existed prior to oil and gas operations by placement of the soil cover, recontour the location and associated areas to a contour that approximates the original contour and blends with the surrounding topography and re-vegetate.

- (A) Construct the soil cover to the site's existing grade and prevent ponding of water and erosion of the cover material. The soil cover shall consist of the background thickness of topsoil or one foot of suitable material to establish vegetation at the site, whichever is greater.
- (B) Seed or plant the disturbed areas the first growing season after closing the below-grade tank. Drill on the contour whenever practical or by other division-approved methods. The goal is to obtain vegetative cover that equals 70% of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. During the two successive growing seasons that prove viability, there shall be no artificial irrigation of the vegetation.
 - (C) Repeat seeding or planting until it successfully achieves the required vegetative cover.
- **(D)** If conditions are not favorable for the establishment of vegetation, such as periods of drought, contact the Aztec OCD office to discuss possibly delaying seeding or planting until soil moisture conditions become favorable or using additional techniques such as mulching, fertilizing, irrigating, fencing or other practices.
- (E) Notify the Aztec OCD office (Brandon Powell 334-6178, Ext 15) when the area has been seeded or planted <u>and</u> when it successfully achieves re-vegetation.

Area is needed for operations. Upon abandonment, seeding will be deferred to the BLM / Tribal requirements per the BLM / OCD MOU.

District I '
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003 Jubmit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Releas	se Notificati	ion	and Corre	ctive Actio	n			
						OPERATOR	₹	☐ Initial	Repor	rt 🗵	Final Report
Name of Company: Energen Resources, Inc.			Contact: E	d Hasely							
			Felephone No: 5	05-324-4131							
Facility Nam	e: Wright S	State Com #1	Е		1	Facility Type: O	il/Gas Well Site				
Surface Owi	ner: State			Mineral Owi	ner:	State		Lease No.	,		
				LOCATI	ON	OF RELEA	SE				
Unit Letter	Section 36	Township 32N	Range 13W	Feet from the		rth/South Line	Feet from the	East/West Li		County San Juar	
			Lati	tude_36.93996_		Longitude	-108.14799_				
				NATUF	RE (OF RELEAS	E				
Type of Relea	se: NO REL	EASE				Volume of Relea	ise:	Volume Rec	overe	d:	
Source of Rel	ease:					Date and Hour	of Occurrence:	Date and Ho	our of	Discove	ery:
Was Immedia	te Notice Gi	iven?	es 🔲 N	lo 🗌 Not Requi	red	If YES, To Who	m?				
By Whom?						Date and Hour:					
Was a Watero	ourse Reac		es 🗌 N	lo		If YES, Volume Impacting the Watercourse.					
Describe Cause THERE WAS ONLY TO SA	se of Proble NO PROBL	m and Remed	lial Action	Taken.*		FORM IS FILLEI	O OUT TO SERV	E AS A COVE	R FOR	LAB A	ANALYSES -
Describe Area	Affected at	nd Cleanup A	ction Tak	en.*							
regulations all public health of should their op	operators are r the enviror erations hav ment. In add	e required to rement. The ac e failed to ade tion, NMOCI	eport and/oceptance of quately in acceptan	or file certain relean of a C-141 report by vestigate and reme	se no y the diate	te best of my know of the control of	form corrective ac as "Final Report" t pose a threat to	ctions for releas does not relieve ground water, s	es while the of urface	ch may operator of water, h	endanger of liability numan health
	501	1 by				<u>O</u>	IL CONSER	VATION D	IVIS	<u>ION</u>	
Signature: Printed Name:	Ed Hasely	esv (Approved by Distri	ct Supervisor.				
Title:	Sr. Enviro	onmental Engi	neer		1	Approval Date:		Expiration Da	te:		
E-mail Addres	s ed.hasely@	venergen.com			(Conditions of Appr	oval		Attached		
Date: 4/11/12	P	hone: 505-324	-4131 / 50	5-330-3584(cell)							

^{*} Attach Additional Sheets If Necessary



TOTAL PETROLEUM HYDROCARBONS

•			
Client:	Energen	Project #:	03022-0001
Sample ID:	Pit Comp	Date Reported:	02-29-12
Laboratory Number:	61210	Date Sampled:	02-23-12
Chain of Custody No:	13436	Date Received:	02-23-12
Sample Matrix:	Soil	Date Extracted:	02-24-12
Preservative:	Cool	Date Analyzed:	02-24-12
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

25.7

6.4

ND = Parameter not detected at the stated detection limit.


References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Wright State Com 1E





EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Energen	Project #:	03022-0001
Sample ID:	Pit Comp	Date Reported:	02-27-12
Laboratory Number:	61210	Date Sampled:	02-23-12
Chain of Custody:	13436	Date Received:	02-23-12
Sample Matrix:	Soil	Date Analyzed:	02-27-12
Preservative:	Cool	Date Extracted:	02-23-12
Condition:	Intact	Analysis Requested:	BTEX
		Dilution:	10

	Dilation.	10
		Det.
	Concentration	Limit
Parameter	(ug/Kg)	(ug/Kg)
Benzene	ND	10.0
Toluene	ND	10.0
Ethylbenzene	ND	10.0
p,m-Xylene	ND	10.0
o-Xylene	ND	10.0
Total BTEX	ND	

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	87.7 %
	1,4-difluorobenzene	101 %
	Bromochlorobenzene	103 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846

USEPA, December 1996.

Comments:

Wright State Com 1E

Analyst

ReVIEW

5796 US Highway 64, Farmington, NM 87401

Ph (505) 632-0615 Fx (505) 632-1865

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (970) 259-0615 Fr (800) 362-1879





Chloride

Project #: 03022-0001 Client: Energen Sample ID: Pit Comp Date Reported: 02-29-12 Lab ID#: 61210 Date Sampled: 02-23-12 Sample Matrix: Soil Date Received: 02-23-12 Preservative: Date Analyzed: 02-24-12 Cool Condition: Intact Chain of Custody: 13436

Parameter Concentration (mg/Kg)

Total Chloride

95

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Wright State Com 1E

Analyst

and order in com-

laboratory@envirotcch=inecom

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879



March 5, 2012

New Mexico State Lands Office 310 Old Santa Fe Trail Santa Fe, New Mexico 87504

Re:

Below Grade Tank Closure

Wright State Com #1B and #1E

Dear Sirs:

Energen Resources plans to close a below grade tanks located on the subject well locations. You are on record as the surface owner where these wells are located. New Mexico Oil Conservation Division (NMOCD) rules require notification to the surface owner of our plans to close the below grade tank. NMOCD rules and guidelines will be followed.

Wright State Com #1B - Unit Letter H, Section 36, Township 32N, Range 13W Wright State Com #1E - Unit Letter I, Section 36, Township 32N, Range 13W

If there are any questions or concerns, please contact me at 505-330-3584.

Sincerely,

Ed Hasely


Sr. Environmental Engineer

Energen Resources

Well File Cc: Correspondence

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
Complete Items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailplece,	A Signature Agent Addressee B. Received by (Printed Name) C. Date of Delivery
or on the front it space permits. 1. Article Addressed to: NM State Levels Office 310 Old Senda Fe Trank	D. is delivery address different from item 1?
Souther Fe, NM 87504	3. Service Type. A Certified Mall Depress Mall Requirement Marchandise Diffusion Mall D.C.O.D. 4. Restricted Delivery? (Extra Fee) Degree Yes
2. Article Number 7009 2820 0	000 5801 7883

water a state of the state of t



Ed Hasely

From:

Ed Hasely

Sent:

Monday, March 05, 2012 4:00 PM

To: Subject:

'Kelly, Jonathan, EMNRD' BGT Closure Notification

Jonathan – This email is to notify the OCD that Energen plans on closing the BGTs on the following locations in the near future.

Wright State Com #1B – Unit Letter H – 36 - 32N - 13W


Wright State Com #1E – Unit Letter I – 36 – 32N – 13W


Let me know if you have questions. Thanks.

Ed Hasely

Energen Resources Corporation

Sr. Environmental Engineer ed.hasely@energen.com
Office: (505) 324-4131
Cell: (505) 330-3584







April 11, 2012

New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

Attn: Brandon Powell

Re: Wright State Com #1E

Below Grade Tank Closure

Dear Mr. Powell:

Enclosed is the final C-144 Form for the Below-Grade Tank closure on the subject well location.

If there are any questions or concerns with this submittal, please contact me at 505-324-4131.

Sincerely,

Ed Hasely

Sr. Environmental Engineer

Energen Resources

Attachments: Final C-144

Closure Report

C-141

Lab Reports

Notification Documentation

Photo

Cc: **HSE File**

> Facility File Correspondence