



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD MAY 3 '12

OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/25/12 Operator C.O.P. API #30-0 392452200

Property Name San Juan 31-6 Well No. 225 Location: Unit K Section 31 Township 31 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 100 Intermediate N/A Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>	<u>N/A</u>	<u>6</u>			Steady Flow	
10 min	<u>0</u>	<u>N/A</u>	<u>6</u>			Surges	
15 min	<u>0</u>	<u>N/A</u>	<u>6</u>			Down to Nothing	
20 min						Nothing	<u>✓</u>
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: No Pressure on Btt Tested Through 1" Valve

By D. Roberts
Production Specialist
(Position)

Witness Paul Wicke

E-mail address Danny.K.Roberts@ConocoPhillips.com