



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 16-MAY-2012 Operator CONOCO API #30-0 95-24117

Property Name COLE A Well No. 1E Location: Unit 1 Section 35 Township 28 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing 186 Intermediate Casing 201.2 Bradenhead 18.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	1		201		
10 min			207		
15 min			215		
20 min			219		
25 min			222		
30 min			226		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>X</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u> </u>	
Gas & Water <u> </u>	
Water <u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

RCVD MAY 17 '12

CLEAR X FRESH X SALTY SULFUR BLACK

OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 12

INTERMEDIATE DIST. 3

REMARKS:

OPENED THE BRADEN HEAD AND WATER
CAME OUT FOR 1 SECOND AND NOTHING CAME OUT. AFTER 5
MINUTES WATER BEGAN FLOWING AGAIN FILLING A 5 GAL BUCKET IN
35 SECONDS

By Russell Ellett Witness John DeBorja

M50
(Position)

E-mail address