



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-23-12 Operator Black Hills API #30-0 39-24112

Property Name Jicarrilla 460 Well No. 2 Location: Unit 14 Section 21 Township 30 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing — Intermediate — Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>0</u>		
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<input checked="" type="checkbox"/>
Nothing	
Gas	<input checked="" type="checkbox"/>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Bradenhead had a slight blow.

By John Dub

Witness —

(Position)

E-mail address —

