



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 5 '12

OIL CONS. DIV.

DIST. 3

Date of Test 6/5/2012 Operator Burlington API #30-0 139-07583

Property Name San Juan 29-7 Unit Well No. 75 Location: Unit G Section 23 Township 29 Range 7

Well Status (Shut-In) or Producing) Initial PSI: Tubing 147 Intermediate NA Casing 148 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	148		
10 min	0	1	148		
15 min	0	1	148		
20 min	0	1	149		
25 min	0	1	149		
30 min	0	1	149		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.1 INTERMEDIATE NA

REMARKS:

House Tap runs to residence West of location, no longer runs to houses east. No H₂S on BH

By

Jennifer D. Bickley
MSO
(Position)

Witness

Jonathan D. Kelly

E-mail address _____