



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUN 5 '12

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/05/2012 Operator Burlington API #30-04539-2481
Property Name San Juan 29-7 Unit NP Well No. 560 Location: Unit 6 Section 23 Township 2A Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 1 Intermediate NA Casing 45 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0		46			
10 min	0		47			
15 min	0		47			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Producing off of casing. No H₂S on BH

By

Jennifer D. Bickley
MSO
(Position)

Witness

Jonathan D. Kelly

E-mail address _____