



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUN 5 '12
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 6/5/2012 Operator Burlington API #30-0 39-30440
Property Name San Juan 297 well Well No. 67M Location: Unit K Section 23 Township 21 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 145 Intermediate 0 Casing 185 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	185	0	185
10 min	0	0	185	0	185
15 min	0	0	185	0	185
20 min	1	1	1	1	1
25 min	1	1	1	1	1
30 min	1	1	1	1	1

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

CO 10 min Intermediate, no puff, nothing on BH no fluids or H₂S.

By

Jennifer Bickley
MSO
(Position)

Witness

Gonath D Kelly

E-mail address _____