

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	BP America Production Company	Contact:	Courtney Cochran
Address	200 Energy Ct. Farmington, NM 87401	Telephone No.:	505-326-9457
Facility Name:	Kayasyahi #1	Facility Type:	Natural Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	API No.:	300450719300
----------------	---------	----------------	---------	----------	--------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	T28N	R09W	840	North	1700	East	San Juan

Latitude 36.63801 Longitude 107.7367

#### NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	127 MCF	Volume Recovered	none
Source of Release	Pressure Safety Valve	Date and Hour of Occurrence	5/9 12 pm - 5/10 3 pm	Date and Hour of Discovery	5/11/2012
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

RCVD MAY 17 '12  
OIL CONS. DIV.  
DIST. 3



Describe Cause of Problem and Remedial Action Taken.\*

Nut was found in suction controller thereby allowing the suction scrubber to overpressure and cause PSV to lift. Compressor flagged/tagged and blown down. Well is shut-in. Issue under investigation.

Describe Area Affected and Cleanup Action Taken.\*

Natural gas dissipated to atmosphere, so no clean up action possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran		Approved by Environmental Specialist: 	
Title: Field Environmental Advisor		Approval Date: 5/25/2012 Expiration Date:	
E-mail Address: Courtney.Cochran@bp.com		Conditions of Approval:	
Date: 5/14/2012 Phone: 326-9457		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

nJK 1214628963