<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

						OPERATOR						
Name of Company: BP America						Contact: Jeff Peace			_			
Address: 200 Energy Court, Farmington, NM 87401						Telephone No. (505) 326-9479						
Facility Name: Florance 100						Facility Type: Natural Gas Well						
Surface Owner: Federal Mineral Owner:						Federal			API No. 3004520064			
Surface OW	ner. reder	<u>шт</u>										
	,					N OF REI	_ <u> </u>					
Unit Letter Section 7 Township 8 Range 8 Feet from the South 1170 South						South Line	Feet from the 945	East/West Line East		County San Juan		
Latitude 36.77837 Longitude 107.71039												
Type of Release Natural Gas NATURE OF RELEASE Volume of Release: 718 Mcf est. Volume Recovered: None												
					Volume of Release: 718 Mcf est. Volume Recovered: None						7/2/2012	
Source of Release: Unknown						Date and Hour of Occurrence: Date and Hour of Discovery: 5/						5/3/2012
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required If YES, To Whom? Brandon Powell												
By Whom? Jeff Peace						Date and Hour: 9:05 AM on 5/10/12 left message						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*						RCVD MAY 11 12						
						OIL CONS. DIV.						
DIST. 3												
Describe Cause of Problem and Remedial Action Taken.* The well was found logged off and not producing on 5/3/2012. Examination of production records showed a decline in well tubing pressure, indicating gas from the well was released to the atmosphere. Volume estimate assumes well continued producing, but it is possible the well logged off and quit producing soon after the possible gas release started. A root cause failure analysis (RCFA) will be performed on the well production equipment to determine the exact cause of the gas release and get a better estimate of the release volume. A final C-141 will be submitted after the RCFA. The well is currently shut in.												
Describe Area Affected and Cleanup Action Taken.* The released gas dissipated into the atmosphere so no cleanup action was possible.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Off Peace						OIL CONSERVATION DIVISION						
Printed Name: Jeff Peace						Approved by Environmental Specialist:				som s. Kelly		
Title: Field Environmental Advisor						Approval Date: 6/15/2012 Expiration Date:						
E-mail Address: peace.jeffrey@bp.com						Conditions of Approval:			Attached			
Date: May	y 10, 2012		Phone:	(505) 326-9479								

nJK1216740434