



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

RCVD JUN 19 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-19-12 Operator Burlington API #30-0 45-20258
Property Name Florence Well No. 1 Location: Unit 26 Section 26 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 24 Intermediate 4 Casing 30/8 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	2	4	30	0	228
10 min	2	4	104	0	122
15 min	4	4	162	0	126
20 min	2	4	162		
25 min	2	4	166		
30 min	2	4	166		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	/	
Surges		
Down to Nothing		
Nothing		
Gas		/
Gas & Water		
Water	/	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 26 INTERMEDIATE 0

REMARKS:

Black to Clear in 1 second. - Started flowing in 10 seconds. Water = 5 barrels Clear Water in 30 min. But blew to Vapors in 1 min - Vapors 10-15

By Robert Chavez

Witness Monica Kuehling

(Position)

E-mail address

Well Started Producing at start of int. test.