



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUN 19 '12

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-19-12 Operator Burlington Resources API #30-0 45-23817
Property Name Graveling 2 Well No. 2A Location: Unit Section 22 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 110 Intermediate N/A Casing 116 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>2</u>		<u>118</u>		
10 min	<u>2</u>		<u>118</u>		
15 min	<u>2</u>		<u>120</u>		
20 min	<u>2</u>		<u>120</u>		
25 min	<u>2</u>		<u>122</u>		
30 min	<u>2</u>		<u>122</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>✓</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	<u>/</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 4

INTERMEDIATE N/A

REMARKS:

4.6 barrels flowed water immediately when opened.
4.6 barrels clear water

By Robert Chavez

Witness Monica Kuehling

(Position)

E-mail address