

District I
1625 N. French Dr , Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-24306

OPERATOR

X Initial Report ☐ Final Report

Name of Company Mallon Oil Company	Contact Ron Sansoni	
Address P. O. Box 2797	Telephone No. 970-382-9100	
Facility Name Jicarilla 459 No. 3	Facility Type Gas Well	
Surface Owner Jicarilla Apache Tribe	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter B	Section 18	Township 30N	Range 03W	Feet from the 1658'	North/South Line North	Feet from the 1901'	East/West Line East	County Rio Arriba
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered Est. 10 bbls
Source of Release Production Tank	Date and Hour of Occurrence 9/1/00 Morning	Date and Hour of Discovery 9/1/00 9:30 AM
Was Immediate Notice Given? Required X Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Bob Blaylock, Mallon Oil Company / Denny Foust, O.C.D.	
By Whom? Jimmy Costalez	Date and Hour 9/1/00 10:35 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Well was being tested to production tank at 11:00 AM 8/31/00, Gauge 1' 4" this morning tank was full spilling 10 bbls of water into dyke. Used vacuum truck to recover water from dyke and switched out of tank back to the water line.		
Describe Area Affected and Cleanup Action Taken.* Dyke area is still wet on the North side. Vacuum truck was used to recover water from the dyke area		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>RSansoni FOR JIM COSTALEZ</i>	OIL CONSERVATION DIVISION	
Printed Name Jimmy Costalez	Approved by <i>Denny Foust for Frank Chavez</i> District Supervisor:	
Title: Production Foreman	Approval Date: <i>9/14/00</i>	Expiration Date.
Date: 9/1/00 Phone: 970-486-0313	Conditions of Approval:	Attached <input type="checkbox"/>

nJK1217251430