District I - (505) 393-6161 P.O. Box 1940 Hobbs, NM 88241-1280 District II - (505) 748-1283 811South First Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Road Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street Santa Fe, New Mexico 87505 (505) 827-7131

Form C-141 Originated 2/13/97

JAN 2000

Submit 2 copies to: Appropriate District Office in accordance with Rule 116.

Release Notification and Corrective Action															
30-045-22376 OPERAT											Initial Repo	rt 💆	Final	Report	
Name:	Burlington Resources							Contact: Ed Hasely							
Address:	ddress: P.O. Box 4289 Farmington NM 87499								5) 326-9537						
Facility Name: TURNER B COM 1A									Well						
Surface Owner: State Mineral Owner:								State	Lease Number:		E-2	757-3-NM			
LOCATION OF RELEASE															
Unit Letter	Section	Township	Range	Feet From	m the	North/South	Line	Feet From the	East/West Li	ne Coun	ty: San Juan				
F					Nort	orth 1548 West				y Dun your					
	NATURE OF RELEASE														
Type of Release: Oil								e of Release:	30 bbls.		olume Recover	red:	25	bbls.	
Source of Release: Stuffing Box								Date and Hour of Occurence:			Date and Hour of Discovery				
Was Immediate Notice Given? ✓ Yes ☐ No ☐ Not Required								1/17/00 1/17/00 If Yes, To Whom? Denny Foust							
By Whom? Ed Hasely								Date and Hour: 1/17/00 4:00:00 PM							
THE PARTY OF THE P								If YES, Volume Impacting the Watercourse. 0							
Was a Watercourse Reached? Yes No If YES, Volume impacting the Watercourse. 0 If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)															
NA	NA														
Describe Caus	e of Probl	em and Ren	nedial Ac	tion Take	n. (Atta	ch Additiona	l Sheets	If Necessary)							
A stuffing box leak allowed the pumped fluids to leak out onto the frozen ground.															
Describe Area	Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)														
The released fluids were mainly contained on location, but an area approximately 2 ft wide by 40 ft long was impacted off location. A vacuum truck recovered 25 bbls of free liquids. The impacted soils were excavated and landfarmed onsite.															
are required to C-141 report b contamination	hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
Signature: 1/2 / Approved b								OIL CONSERVATION DIVISION De y Jeen Jeen Jeen Jeen Jeen Jeen Jeen J							
	ニこと	14900	7			District Sur		· · · ·			rez				
Title: Environmental Representative Approva									000	Expiratio					
Date: 1/17/66 Phone: (505) 326-9841 or 326-9842						Conditions of Approval:					Attached:				