

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division


2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141

Originated 2/13/97



Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Gregg Wurtz
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9537
Facility Name:	ALLISON UNIT COM	Facility Type:	Gas Well

Surface Owner:	fee	Mineral Owner:	fee	Lease Number:	FEE
----------------	-----	----------------	-----	---------------	-----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
N	09	032N	006W	900	South	1490	West	

NATURE OF RELEASE

Type of Release:	Coal seam water	Volume of Release:	115 bbls.	Volume Recovered:	110 bbls.
Source of Release:	Coal well water tank, vandels opened valve	Date and Hour of Occurrence:	2/19/00 9:00:00 PM	Date and Hour of Discovery:	2/20/00 6:30:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour:	2/22/00 7:00:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Vandalism of tank valve. Remedial action included removing water by pump truck and disposing properly.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Water was completely contained in earthen bermed area surrounding tank. No futher cleanup action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>J. Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name:	Gregg Wurtz	Approved by:	<i>Henry G. Foust</i>
Title:	Environmental Representative	District Supervisor:	<i>for Frank Chavez</i>
Date:	Phone: (505) 326-9537 or (505) 326-9841	Approval Date:	2/28/2000
		Expiration Date:	
		Conditions of Approval:	Attached: <input type="checkbox"/>

DGF0000033