

District I - (505) 393-6161
P.O. Box 1940
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name: Burlington Resources	Contact: Ed Hasely	
Address: P.O. Box 4289 Farmington NM 87499	Telephone No.: (505) 326-9537	
Facility Name: Jillson Federal SWD	Facility Type: SWD Facility	
Surface Owner: Federal	Mineral Owner:	Lease Number:

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: Rio Arriba
F	8	24N	3W	2305	North	2415	West	

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls.	Volume Recovered: 15 bbls.
Source of Release: Produced Water Storage Tanks	Date and Hour of Occurrence: 2/28/00	Date and Hour of Discovery: 2/28/00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Corrosion caused a small hole in the bottom of one of the storage tanks at the SWD facility. All fluids were contained within the bermed area. Free liquids were recovered using a vacuum truck.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All fluids were contained within the bermed area. Soils will be raked after it dries out. The storage tank is being repaired.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ed Hasely</i>	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by: <i>Denny G. Fout</i>	District Supervisor: <i>For Frank Chavez</i>
Title: Environmental Representative	Approval Date: 3/3/2000	Expiration Date:
Date: 3/1/00 Phone: (505) 326-9841 or 326-9842	Conditions of Approval:	Attached: <input type="checkbox"/>

Not entered in computer NJK1217333860