## District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811South First

Artesia, NM 88210 District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

## State of New Mexico

Form C-141 Originated 2/13/97

## **Energy Minerals and Natural Resources Department**

## **Oil Conservation Division**

2040 South Pacheco Street Santa Fe, New Mexico 87505 (505) 827-7131



Submit 2 copies to: Appropriate District Office in accordance

<u>District IV - (505) 827-7131</u>			E 23	OILCO	N. DIV	with Rule 116.
Release Notification and Corrective Action						
						Final Report
Name: Burlington Resources	Co	ontact: (	regg Wurtz	CAPE.	26,198	
Address: P.O. Box 4289 Farmington NM 87499		Telephone No.: (505) 326-9537				
Facility Name: SAN JUAN 32-9 UNIT 1	8R Fa	Facility Type: Gas Well				
		DIM	Lease Number:		NR AGE OFF	206
Surface Owner: BLM Mineral Ow	ner:	BLM	Lease Number:		NMSF-078	386
LOCATION OF RELEASE						
Unit Letter   Section   Township   Range   Feet From the   Nor	th/South Li	ne Feet From	the East/West Lin	ne County:	San Juan	
K 17 031N 009W 1615	South	1780	west			
NATURE OF RELEASE						
Type of Release: Condensate	Vo	olume of Release:	35 bbls.	Volum	ne Recovered:	32 bbls.
Source of Release: Condensate tank overflow		Date and Hour of Occurence: 2/22/00 7:00:00 AM		Date:	Date and Hour of Discovery 2/23/00 6:00:00 PM	
Was Immediate Notice Given? ✓ Yes ☐ No ☐ Not Requ	uired If	If Yes, To Whom? Denny Foust, OCD Aztec, NM				
By Whom? Gregg Wurtz	Date and Hour: 2/24/00 2:30:00 PM					
Was a Watercourse Reached? ☐ Yes ✓ No	If YES, Volume Impacting the Watercourse. 0					
If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)						
No watercourse or surface water body was impactedl.						
	,					
Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)						
Historical well condensate production significantly increased for unknown reasons causing storage tank to overflow into secondary containment prior to						
scheduled routine tank pumping. Released condensate was removed imeadiately after discovery. Soils were removed within 12 hours of discovery. Tank and pit tank moved and an estimated 10 cu. yds. of material was excavated from within the bermed area and landfarmed on site.						
Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)						
All condensate contained within tank secondary containment. Contaminated soil excavated vertically and horizonitally to the extent of no visible contamination.						
I handly contifue that the information already above in the good complete to	the best of me	u lavoudodao and us	dowtand that number	to MMOCD	les and regulations	all an am tam
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a						
C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the						
operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Signature: Great Wurty		L'eng L Four				
I I mice wante.	proved by strict Supers	visor: Ca	F. www		,,,p, <del>z</del>	
01299 10011-2	proval Date		2000	Expiration D	ate:	
• • • • • • • • • • • • • • • • • • • •	onditions of A	Approval:		At	tached:	
	20.00					·