


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30-039-25845

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name JICARILA B 2A	Facility Type PRODUCTION FACILITY

Surface Owner JICARILLA APACHE TRIBE	Mineral Owner JICARILLA APACHE TRIBE	Lease No. CONT 106
---	---	-----------------------

LOCATION OF RELEASE

Unit Letter I	Section 25	Township 26N	Range 04W	Feet from the 1540	North/South Line FSL	Feet from the 1185	East/West Line FEL	County RIO ARRIBO
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------------

NATURE OF RELEASE

Type of Release PRODUCED WATER & OIL	Volume of Release 2-OIL 12-WTR BBLS	Volume Recovered 2-OIL 10-WTR BBLS
Source of Release PRODUCED WATER TANK	Date and Hour of Occurrence 11/17/00 AM	Date and Hour of Discovery 11/17/00 3:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? DENNY FOUST, KURT SANDOVAL	
By Whom? SHIRLEY EBERT	Date and Hour 11/17/00 4:00 4:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 2" TANK VAVLE FROZE AND CRACKED. 2 BBLS OF OIL AND 10 BBLS OF WATER WAS PICKED UP BY A VACUUM TRUCK.

Describe Area Affected and Cleanup Action Taken.*
THE SPILL OCCURRED INSIDE THE BERMED AREA. THE AREA WILL BE REMEDIATED BY NMOCD GUIDELINES.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary Ledbetter</i>	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by <i>Denny Foust</i> District Supervisor: <i>for Frank Chavez</i>	
Title: SHEAR SPECIALIST	Approval Date: <i>12/13/00</i>	Expiration Date:
Date: <i>12/12/00</i> Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

nJK1217857021