

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
Aztec District Office  
1000 Rio Brazos Road  
Aztec NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://lemnrd.state.nm.us/ocd/District III/3district.htm](http://lemnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-10-04 Operatr PATINA SAN JUAN, INC. API# 30-039-06655

Property Name TRIBAL C Well No. 1 Location:Unit M Section 6 Twp 26N Range 03W

Pressure (Shut-in or Producing) Tubing X Intermediate 0 Casing 40 Bradenhead 0  
45

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**

TIME	PRESSURES:		Steady Flow	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING			
5 minutes		<u>40</u>		<u>NO</u>	
10 minutes		<u>40</u>	Surges	<u>NO</u>	
15 minutes		<u>40</u>	Down to Nothing	<u>10 sec</u>	
20 minutes			Nothing	<u>N/A</u>	
25 minutes			Gas	<u>yes</u>	
30 minutes			Gas & Water	<u>NO</u>	
			Water	<u>NO</u>	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD less than 5 psi INTERMEDIATE \_\_\_\_\_

REMARKS: \_\_\_\_\_

By Tson Blas \_\_\_\_\_ Witness \_\_\_\_\_

(Position)

