NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

Aztec District Office 1000 Rio Brazos Road Aztec NM 87410

(505) 334-6178 FAX: (505) 334-6170 hhtp:\\emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

| Date of Test 6-16-89 Operato PATINA SAN JUAN, INC. | | | | | | / API#30-039-23475 | | | | | | |
|---|------------------------------------|-------------|--------|----------------|----------------------|-----------------------|-----------------|------------------------|---------|-------------|----------------|--|
| Property Name TRIE | BAL C | Well No. | 1E | Location:Unit | _F_ | Section | 6_ | Twp | 26N | Range | 03W | |
| Pressure (Shut-in or Pr | oducing) | Tubing_ | | Intermediate | <u></u> | _Casing_ | | Bra | adenhea | d | | |
| OPEN BRA | DENHEAD A | ND INTERME | EDIATE | TO ATMOSPH | IERE I | NDIVIDU | JALL' | Y FOR | 15 MINU | JTES EA(| CH | |
| | PRESSURES: IME INTERMEDIATE CASING | | | | BRADENHEAD FLOWED | | | INTERMEDIATE FLOWED | | | | |
| 5 minutes | | | | Steady Flow | | | | | | | | |
| 10 minutes | | | | Surges | | | | | <u></u> | | | |
| 15 minutes | | | | Down to Nothir | ng | | | | | | | |
| 20 minutes | | | | Nothing | | ··· | | | | | | |
| 25 minutes | | | | Gas | <u>-</u> | | | ļ | | | | |
| 30 minutes | | | | Gas & Water | | | | ļ | | | | |
| | | | | Water | - . | - - | | | | | | |
| If bradenhead flowed water, check all of the descriptions that apply below: | | | | | | | | | | | | |
| C | CLEAR | FRESH | | SALTY | SULF | UR | E | BLACK_ | | | | |
| 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE | | | | | | | | | | | | |
| REMARKS: A/ | ell | HAS | be | en p | lug | , | | - A O | 3101112 | Bass | | |
| · | | | | | | | | 6 | AU 8 | | | |
| | | | | | | | [- - | + Off | | 10g = | } — | |
| By Sarry Bright Witness | | | | | | | | | | | | |
| By Lang B. (Position) | | | | | | | | | ELZR. | 200 | | |