



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 9-23-04 Operator MAUON OIL API #30-0 39-24086

Property Name JIC. 458 Well No. 20A Location: Unit 0 Section 7 Township 36N Range 3W

Well Status (Shut-In) or Producing) Tubing X Intermediate      Casing      Bradenhead     

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>    </u>	<u>    </u>	Steady Flow <u>    </u>	
10 minutes	<u>    </u>	<u>    </u>	Surges <u>    </u>	
15 minutes	<u>    </u>	<u>    </u>	Down to Nothing <u>    </u>	
20 minutes	<u>    </u>	<u>    </u>	Nothing <u>    </u>	
25 minutes	<u>    </u>	<u>    </u>	Gas <u>    </u>	
30 minutes	<u>    </u>	<u>    </u>	Gas & Water <u>    </u>	
			Water <u>    </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     


5 MINUTE SHUT-IN BRADENHEAD      INTERMEDIATE     

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Larry Stupling  
Plant Foreman  
(Position)

Witness \_\_\_\_\_



BA valve has not been dug out.  
pic 77