

NEW MEXICO ENERGY, MONICALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX; (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

	0		Hack Hills	1	4-4-5
Date of Test_	9-21-04	Operator	MALLON DIC	API #30-0 3 9	1 - 25758
					nship30N Range3W
Well Status(S	hut-In of Producin	g) Tubing 18	Intermediate 4/4	Casing 168 Brade	enhead <u>**</u>
OPEN BRA	DENHEAD AND I	NTERMEDIATE	TO ATMOSPHERE	INDIVIDUALLY FOR	15 MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Fl	ow	
10 minutes			Surges		
15 minutes			Down to	Nothing	
20 minutes			Nothing_		
25 minutes			Gas		
30 minutes			Gas & W	ater	
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAF	R FRESH	SALTY	SULFUR	BLACK 12	3456
5 MINUTE SH	UT-IN BRADENI	IEAD	INTERMEDIATE		Per 3
REMARKS:		,		1292	1000 S
				To be a second of the second o	s m
	······································			THE REAL PROPERTY.	61.01.11.20.20
				1-	
By Line	+Dlank	Wit	ness		
Ze	are operator				
(Positi	ion)				