



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III3distrct.htm](http://emrdr.state.nm.us/ocd/District%20III3distrct.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-23-04 Operator MAKON ON API #30-0 39-25763

Property Name JIC. 459 Well No. 17-9 Location: Unit 6 Section 17 Township 30N Range 3W

Well Status(Shut-In or Producing) Tubing _____ Intermediate _____ Casing X Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>—</u>	<u>18</u>	Steady Flow	
10 minutes	<u>—</u>	<u>19</u>	Surges	
15 minutes	<u>—</u>	<u>19</u>	Down to Nothing	
20 minutes	<u>—</u>	<u>22</u>	Nothing	<u>6</u>
25 minutes	<u>—</u>	<u>24</u>	Gas	
30 minutes	<u>—</u>	<u>28</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 6 INTERMEDIATE _____

REMARKS:

By Langley
Don't Foreman
(Position)

Witness _____



grease + dirt on Bit valve - Does not appear to have been operated recently.