



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-23-04 Operator MAWON OIL API #30-0 39-25906

Property Name Jic 459 Well No. 17-11 Location: Unit 0 Section 17 Township 30 Range 3

Well Status (Shut-In or Producing) Tubing Intermediate Casing Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u> </u>	<u> </u>	Steady Flow <u> </u>	
10 minutes	<u> </u>	<u> </u>	Surges <u> </u>	
15 minutes	<u> </u>	<u> </u>	Down to Nothing <u> </u>	
20 minutes	<u> </u>	<u> </u>	Nothing <u> </u>	
25 minutes	<u> </u>	<u> </u>	Gas <u> </u>	
30 minutes	<u> </u>	<u> </u>	Gas & Water <u> </u>	
			Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

WELL S-I RE-DRILL

By Darryl Stimp
Plant Foreman
(Position)

Witness



BH valve has not been dug out.
pic 74