



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-3-12 Operator Tom Star API #30-0 45-31935
Property Name HSLoeFed B Well No. 45 Location: Unit Section 23 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate N/A Casing 19 Bradenhead 99

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		19		
10 min	0		19		
15 min	0		19		
20 min	0		19		
25 min	0		19		
30 min	0		19		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	DIST. 3
Surges <u> </u>	OIL CONS. DIV.
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u> </u>	RCVD JUL 3 '12
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7 INTERMEDIATE N/A

REMARKS: Gas analysis taken on BH - Me/Light to light in 6 seconds
really (light) blow at 5 min - 10 - 15 - 20 - 25 - 30
Gurgling - 5 - 10 - 15 - 20 - 25 - 30

By Raul Calcat
Caldar services
(Position)

Witness Monica Kuehling
submit copy of gas analysis
lu

E-mail address