



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-24-2010 Operator XTU API #30-0 415-30221

Property Name NAVAJO 24 Well No. 41 Location: Unit 6 Section 28 Township 29 Range 14

Well Status(Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	BRADENHEAD			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min		<u>N/A</u>	<u>0</u>		
10 min			<u>0</u>		
15 min			<u>0</u>		
20 min					
25 min					
30 min					
				Steady Flow	
				Surges	
				Down to Nothing	
				Nothing <u>X</u>	
				Gas	
				Gas & Water	<u>RCVD JUL 10'12</u>
				Water	<u>OIL CONS. DIV.</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: OPENED BRADENHEAD NOTHING CAME OUT

By Danny Thompson
Completion Foreman
(Position)

Witness John Dunn

E-mail address _____