



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ood/District III/district.htm](http://emrwd.state.nm.us/ood/District%20III/district.htm)

RCVD MAY 29 '12
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test May 4 2012 Operator Lively Exp API # 30-045-21257
Property Name Lively Well No. 13 Location: Unit A Section 18 Township 28N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 18 Intermediate 121 Casing 228 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	121	228	TL7M	228
10 min	0	121	228	TL7M	228
15 min	0	121	228	TL7M	228
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE TL7M

REMARKS: Test Blew Down to Nothing in A Few Seconds

By [Signature]
[Signature]
(Position)

Witness _____

E-mail address _____