



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III3district.htm](http://emrdd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-25-12 Operator CHEVRON MIDCONTINENT, LP API #30-0 30-045-27578

Property Name TAFOYA L2 #35 Well No. #35 Location: Unit Section -35 Township -32N Range -13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 11.7 Intermediate X Casing 9.8 Bradenhead 1.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>X</u>	<u>9.7</u>		
10 min	<u>0</u>	<u>X</u>	<u>9.7</u>		
15 min	<u>0</u>	<u>X</u>	<u>9.7</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

Oil Cons. Div
District III

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

JUL 05 2012

REMARKS:

By Randy Calder

Witness

Calder services
(Position)

E-mail address Randy.C@calderservices.com