



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-28-12 Operator CHEVRON MIDCONTINENT, LP API #30-0 30-045-28873

Property Name RIPLEY 26 #3 Well No. #3 Location: Unit Section -26 Township -32N Range -13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 83 Intermediate X Casing 84 Bradenhead 0.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>	<u>X</u>	<u>8.4</u>		
10 min	<u>Ø</u>	<u>X</u>	<u>8.4</u>		
15 min	<u>Ø</u>	<u>X</u>	<u>8.4</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing <u>X</u>		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 INTERMEDIATE

REMARKS:

By Randy Calde
Calde services
(Position)

Witness _____

E-mail address Randy.Calde@caldeservices.com

Oil Cons. Div
District III

JUL 05 2012