



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-26-12 Operator Cheliron API #30-045-28886

Property Name Horton Field e37 Well No. 1 Location: Unit - Section 7 Township 31N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 920 Intermediate - Casing 921 Bradenhead 0.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>	<u>Y</u>	<u>92.1</u>		
10 min	<u>Ø</u>	<u>Y</u>	<u>92.1</u>		
15 min	<u>Ø</u>	<u>X</u>	<u>92.3</u>		
20 min					
25 min					
30 min					

Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR - FRESH - SALTY - SULFUR - BLACK -

Oil Cons. Div
District III

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE -

JUL 05 2012

REMARKS:

By Randy culcote

Witness _____

calder services
(Position)

E-mail address Randy.c@calderservices.com