



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emr.nd.state.nm.us/ocd/District III/district.htm](http://emr.nd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-29-12 Operator CHEVRON MIDCONTINENT, LP API # 30-0 30-045-29035

Property Name REDFERN #1 Well No. #1 Location: Unit Section -14 Township -29N Range -13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 34 Intermediate Casing 6.5 Bradenhead 13.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>	<u>X</u>	<u>6.5</u>		
10 min	<u>0</u>	<u>X</u>	<u>6.5</u>		
15 min	<u>0</u>	<u>X</u>	<u>6.5</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X.5 sec</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.3 INTERMEDIATE

REMARKS:

By Randy Calcote
Calder Services
(Position)

Witness

E-mail address Randy.c@calderservices.com

Oil Cons. Div
District III

JUL 05 2012