



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/district.htm](http://emrdd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-28-12 Operator CHEVRON MIDCONTINENT, LP API # 30-0 30-045-31592
Property Name RIPLEY 26 #4 Well No. #4 Location: Unit Section -26 Township -32N Range -13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 43.1 Intermediate X Casing 6.7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	X	6.7		
10 min	0	X	6.7		
15 min	0	X	6.7		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

Oil Cons. Div
District III

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

JUL 05 2012

REMARKS:

By Raul Calderon

Witness

Raul Calderon
(Position)

E-mail address Raul.Calderon@calderon.com