



OIL CONSERVATION DIVISION & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-8-12 Operator ~~Red Williams~~ Kuku API # 30-045-28394
Property Name Angel Peak Well No. 24H #14 Location: Unit H Section 24 Township 27N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 115 Intermediate Casing 130 Bradenhead Vacuum

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>Vacuum</u>	<u>N/A</u>	<u>130</u>		
10 min	<u>0</u>	<u>-</u>	<u>130</u>		
15 min	<u>0</u>	<u>-</u>	<u>130</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	
Surges <u> </u>	
Down to Nothing <u>0</u>	
Nothing <u>Vacuum</u>	
Gas <u> </u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

The Bradenhead HAD A Vacuum, IT Went TO 0 Vacuum In 5 seconds

By E. Wayne Carpenter

Witness

Lease Operator
(Position)

E-mail address wcarpenter@cwpc.us

RCVD JUN 14 '12
OIL CONS. DIV.
DIST. 3