



NEW MEXICO GEOLOGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-8-12 Operator Kukui Redwillow Production API # 30-045-32432

Property Name Frost Well No. 5025 Location: Unit F Section 25 Township 27N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 5 Intermediate Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>25</u>		
10 min	<u>0</u>		<u>25</u>		
15 min	<u>0</u>		<u>26</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	<u> </u>
Surges <u> </u>	<u> </u>
Down to Nothing <u> </u>	<u> </u>
Nothing <u>X</u>	<u> </u>
Gas <u> </u>	<u> </u>
Gas & Water <u> </u>	<u> </u>
Water <u> </u>	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Braden Head Had 0 PSI & 0 volume

By Wayne Carpenter

Witness

Lease Operator
(Position)

E-mail address wcarpenter@rwpc.us

RCVD JUN 14 '12
OIL CONS. DIV.
DIST. 3