

## . NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District II/3distric.htm



## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 7-04-03	Operato	FOUR STAR OIL & GAS	_API #30-0 <i>45-0</i>	7569
Property Name Mexico Feoeral K Well No. 1 Location: Unit M Section 9 Township 28N Range 10W				
Well Status(Shut-In or Producing) Tubing O Intermediate NA Casing < 1 Brandenhead 33				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	<1	Steady Flow		
10 minutes	<1	Surges		
15 minutes	<1	Down to Nothing	g <b>/</b>	
20 minutes	W	Nothing		
25 minutes	W	Gas		
30 minutes	W	Gas & Water		
		Water	- Ai	7777725
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFUR BLAC	ж 🖺	DEC 2003
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE				
REMARKS: Bradenhead blew down through 4 inch needle valve. 8/993				
By tony Witness_				
Operation Technician (Position)				