

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District ill/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test_5-19-04	Operato	r Richardson	_API #30-0 <del></del>	5 28062
Property Name FEI) 72	Well No	2Location: Unit N Se	ection_/C_Towns	hip 28 Range 8W
Well Status(Shut-In or(Producing	Tubing 7	Intermediate <u>NA</u> Casin	ng <u>40</u> Branden	head <u>O</u>
OPEN BRADENHEAD AND IN	TERMEDIATE	TO ATMOSPHERE INDIV	IDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING	-	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothing	<u>,                                      </u>	
20 minutes		Nothing L		
25 minutes		Gas		
30 minutes ·		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFUR BLAC	CK A	10/1/ 20.
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:				
REMARKS:				
By Charl Dunn	Wit	tness		
(Position)	····			