



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District III/3district.htm](http://emrwd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-6-04 Operator Koch Exploration API #30-0 45-31449
Property Name Snick Com Well No. 3224 Location: Unit D Section 32 Township 28 Range 10
Well Status (Shut-In or Producing) Tubing _____ Intermediate _____ Casing _____ Bradenhead O

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing ✓	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE _____

REMARKS: Baseline Bradenhead test. Cement had come to surface
in the Intermediate's Tub.

By Kenneth Coch
Ringer
(Position)

Witness _____

